

ANNUAL SURVEYS.

40735

No. 134 Survey held at London Date, first Survey 2 August Last Survey 24 August 1881
 on the Aradia Master Stoper
 Reg. Book. 1132 Tonnage { Net 417 Built at Bristol When built 1863 Year. 9 Month.
 Gross 418 By whom built Hill Owners Dunson
 Under Dk. 376 Port belonging to London Destined Voyage Limous Bay
 If Surveyed Afloat or in Dry Dock Limchouse Dry dock (State Name of Dock.)

Last Survey, No. 140008 Port of Lon. Classed 14 A1, 81
 Present Condition of the
 Decks Good Treenails Good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shelves do
 Topsides do Ceiling do
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. Y-M When put on 78
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers do Cargo and Main Hatchways do Hatches do
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Yellow Metal repaired. * This vessel appears eligible to remain as classed
damaged with ballast in main hold - * The 3rd lower anchor & 15 fms. of chain cable that were missing have now been replaced by the following viz: 1 anchor weight ex. stock 14-3-14 - proof strain 16-7-3-7. J. Hartness Superint^{dt} 6/5/81. 15³/₄ fms. 1⁵/₁₆" stud link chain cable - break strain 46¹/₂ tons - tensile strain 31 tons - J. Hartness Superintendent 27/4/81. Sunderland.
 Committee's Minute Friday, August, 26th 1881.
 Character assigned Cond 5A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 on the Master
 Reg. Book. Tonnage { Net Built at When built Year. Month.
 Gross By whom built Owners
 Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Arcadia



© 2021

Lloyd's Register
Foundation