

REPORT of SURVEY for REPAIRS, &c.

46/81

40963

(Received at London Office, 25/8/81)

No. 390 on the SS John Mc Intyre Date, first Survey Aug 8th Last Survey Aug 20th 1887

No. in Reg. Book. 390 on the SS John Mc Intyre Master Johnston

TONNAGE under Tonnage Deck 925 Built at Newcastle When built 1863

Ditto of Spar Deck, or Awning Deck 925 Owners J Fenwick & Son Port belonging to London

Ditto of Poop 925 Residence Palmer

Ditto of Raised Qr. Dk. 925 By whom built Palmer Destined Voyage Coal Trade

Ditto of Houses on Deck 925 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Ditto of Forecastle 925 (State Name of Dock)

Gross Tonnage 985 Length of Poop 670 ft. Ditto, Forecastle 670 ft. Ditto, Raised Quarter Deck 670 ft.

Crew Space, as per Rule 670 Years assigned 6.80

Register Tonnage, cut on Beam 670 Character in Register Book SS Lon M3.80

Engine Room 670 Last Survey, No. 39393 Port Lon

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

At present owing to damage.

Portside in Poop Renewed one Stringer plate, one poop Sheerstrake plate, short length of Gunwale angle iron, one length of Waterway Patch Pine 48 feet, 4 Roughtree Stanchions Eng salt, 2 lengths of Rail 26 ft, 2 lengths of Deck Yellow Pine, Deck caulked in wake of damage.

Bottom be coated.

Present Condition of the						
Decks	Good	Treenails	Rivets	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stemson		"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches		"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings		"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places		"	Condition, how ascertained	From SW
Planksheers	"	Keelsons		"	Sails	Good
Sheerstrakes	"	Clamps and Shelves		"	Anchors No. of 3 Bro. 12 & 14 lbs	
Topsides	"	Ceiling		"	Cables Part on SW	Good
Wales	"	Rudder		"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Copper (or Y.M.) Coated When put on new		"	Standing & Running Rigging	"
Engine Room Skylights	Good	Caulking of			Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Bottom, Deck, & Waterways	Good		Hatches	"
Scuppers	Good					
General Observations, Opinion as to Class, &c.						

She is now in an efficient state and eligible to remain as classed.

Leahouse Martindale

The Amount of Entry Fee ... £ ... : ... : ... received by me, 8/9/1888

Certificate (if required) to be sent as per margin... £ ... : ... : ...

Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £ ...)

Committee's Minute Tuesday, September, 6th 1881.

Character assigned



© 2021

Lloyd's Register Foundation

John M. Ingham



© 2021

Lloyd's Register
Foundation