

Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 9. 9. 81)

No. in
Reg. Book.

Survey held at *London*

Date, first Survey *Sept. 3rd* Last Survey *Sept. 5th* 188*1*

499 on the Machinery of the *S. S. Seine*

(Number of Visits *2*)

Tonnage, Gross *3579*

Built at *London*

When built *1859*

Ditto, Net *2200*

Owners *Mil. Cont. + Maint. Co.*

Port belonging to *London*

Diameter of Cylinder *60" x 95"*

Engines made by *J. Watt & Co.*

When made

Length of Stroke *48"*

Boilers made by *Ditto*

When made

Pressure of Steam *55 lbs.*

If Surveyed Afloat or in Dry Dock *S. S. M. Dry dock*

Classed

Years assigned. Character in Register Book. *100A1*

Registered Horse Power *500*

Last Survey No.

Port

Particulars of Repairs and Examination *For Annual Survey*

(State cause of Repairs.)

Vessel placed in dry dock, sea connections examined and found to be in good condition. Propeller and its connections found to be sound. Tail shaft down 1/4" in Stern Bush. Boilers examined. Furnaces and combustion chambers found in good condition. Screwed stays + Fore + Aft stays in steam space in good condition. Shells of Boilers in good condition. Safety Valves examined found to be in good condition and loaded to 55 lbs. per sq. in.

General Observations, Opinion, and Recommendation:— *The Boilers being now in good and safe working condition, renders the vessel eligible in my opinion to remain as classed than the notification B. S. 9. 81 recorded.*

Entry or Registering Fee... £

Survey Fee (per Section 28) ... £

Certificate (if required) to be sent as per margin.

(Travelling Expenses, if any, £)

received by me, *14/9/81*

14/9/1881

Geo. E. Milner

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Tuesday, September, 13th 1881.

Assigned

B. S. 9, 81



Lloyd's Register Foundation

LON666-0487

He submitted that this vessel is
eligible to have the notification
BL. 9.87 recorded subject to
the vessel being again
exposed 12 months as per
Rule

Am

9/9/87



© 2021

Lloyd's Register
Foundation