

Report of Survey for Repairs of Engines and Boilers.

No. _____ (Received at London Office, 16.9.81)
No. in Reg. Book. Survey held at London Date, first Survey 22 Aug Last Survey 27 Aug 1881
295 on the Machinery of the S.S. Perim (Number of Visits 4)
Tonnage, Gross 1329 Built at Glasgow When built 1877
Ditto, Net 1076 Owners R. W. Cousens & Co Port belonging to London
Diameter of Cylinder 31 54 Engines made by London & Glasgow Co When made 1877
Length of Stroke 33 Boilers made by When made 1877
Pressure of Steam 65
Registered Horse Power 150
If Surveyed Afloat or in Dry Dock Commercial S.S. & afloat Classed 100 A1
(State name of Dock.)
Last Survey No. Port Lloyd's Reg. 577

Particulars of Repairs and Examination S.S. No 1
(State cause of Repairs.)
Examined Leacocks & connections & Propeller & found them in good condition
Examined crankshaft cylinders slide valves and pumps & found them in good condition
Examined Boilers & safety valves, found them in safe working condition.

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in safe working condition & eligible in my opinion to have the notification Lloyd's Reg. C. 8 81 recorded in the Register Book

Entry or Registering Fee... £ 1 : 10 :
Survey Fee (per Section 28) ... £ 3 : 3 :
Certificate (if required) ... £ : :
received by me, 21/9/81

C. J. Prosser
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, September, 20th, 1881.
Assigned



LON666-0518

It is submitted that the
machinery of this vessel is
eligible to have the notification
Lloyd's M.C. renewed and
dated 8. 81.

M
15-9-81



© 2021

Lloyd's Register
Foundation