

ANNUAL SURVEYS.

40834

No. Survey held at London Date, first Survey 8th Sept^r Last Survey 22nd Sept^r 1881
(Received at London Office, 24.9.81)
 No. in on the S. "Torrens" Master H. R. Angel.
 Reg. Book. 427
 Tonnage { Net 1276 Built at Sunderland When built 1875 Year. Month. 10th
 { Gross 1335 By whom built J. Laing. Owners A. L. Elder.
 { Under Dk. 1098
 Port belonging to London Destined Voyage Adelaide
 If Surveyed Afloat or in Dry Dock In the Princes Dry Dock.
(State Name of Dock.)

Last Survey, No. 39404 Port of Lon.
 Present Condition of the
 Decks good Treenails Bolts good
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. good When put on 178
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers good Cargo and Main Hatchways good Hatches good.
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

The bottom has been sighted and the yellow metal sheathing repaired. The topsides recaulked from metal line upwards.
 Vessel surveyed with iron kentledge in the hold amidships.
 She appears to be in good and efficient condition and eligible to remain as classed.

Committee's Minute Friday, September, 30th 1881. J. H. Truscott.
 Character assigned A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Year. Month.
 Tonnage { Net Built at When built
 { Gross By whom built Owners
 { Under Dk.
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
(State Name of Dock.)
 Last Survey, No. Port of Classed
 Present Condition of the
 Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
(If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LON 666-0560

(For No. 4 for Annual Survey, when there are no repairs, 4000-6/12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)