

REPORT of SURVEY for REPAIRS, &c.

40843

(Received at London Office, 1. 10. 81)

No. in Survey held at London Date, first Survey 31 Aug Last Survey 29 Sept 1881
 eg. Book. 926 on the Bth Mermaid Master Mosey
 TONNAGE under Tonnage Deck 752 Built at Sunderland When built 1876
 Ditto of Spar Deck, or Awning Deck 752 Owners W. H. Hick Port belonging to Scarbth
 Ditto of Poop 752 Residence Scarbth
 Ditto of Raised Or. Dk. 752 By whom built Bartraen Destined Voyage New Zealand
 Ditto of Houses on Deck 752 If Surveyed Afloat or in Dry Dock Union dry dock
 Ditto of Forecastle 752 (State Name of Dock)
 Gross Tonnage 787
 Crew Space, as per Rule 751
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St^rmer, cut on Bm.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.
 Last Survey, No. 28221 Port Iron Classed 100 A 10 80
 REPAIRS, OR EXAMINATION AS PER RULE S. S. 11-1. 80
 Cause of Repairs to be clearly stated.

*Bottom cleaned and recoated. Sibboon new.
 Surveyed with ballast in the main hold.
 A new anchor now supplied to replace the third bow; -
 19.3-12, test 20.12.3.9. 16th Sep^r 1881. Certificate
 produced and signed by S. S. Lewis.*

Present Condition of the	Keels	Trunnels	Reefs	Keels	Windlass and Capstan	Keels
Decks	do	Breasthooks and Stemson	do	do	Pumps <u>two</u>	do
Waterways	do	Transoms, Pointers, and Crutches	do	do	Boats <u>three</u>	do
Comings	do	Timbers of the Frame at the openings	do	do	Masts, Yards, &c.	do
Upper Deck Beams & Fastenings	do	Ditto Ditto at other places	do	do	Condition, how ascertained <u>from deck</u>	
Lower Deck Beams & Fastenings	do	Keelsons	do	do	Sails <u>well found</u>	
Planksheers	do	Clamps and Shelves	do	do	Anchors No. of <u>30</u> . <u>1 S & 2 Wedges</u>	
Sheerstrakes	do	Ceiling	do	do	Cables <u>complete</u>	
Topsides	do	Rudder	do	do	Hawsers and Warps <u>sufficient</u>	
Wales	do	Copper (or Y.M.)	When put on	do	Standing & Running Rigging <u>good</u>	
Plank (Bottom) and Counter	do	Caulking of		do	Cargo and Main Hatchways <u>do</u>	Hatches <u>do</u>
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Bottom, Deck, & Waterways		do		
		Scuppers	do			

General Observations, Opinion as to Class, &c.
This vessel appears eligible to remain as classed

The Amount of Entry Fee£ " : " : " received by me, 7/10/81
 5/10/81 Special£ 1 : 1 : " Joseph Thomson
 Certificate (if required) } £ : 5 : "
 to be sent as per margin... }

(Travelling Expenses, if any, £)
 Committee's Minute Tuesday, October, 4th 1881.
 Character assigned 100 A
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 © 2021 Lloyd's Register Foundation
 LON666-0570

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.