

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey July 15th Last Survey Aug 46th 18 81
 No. in on the SS Sunnibin Castle Master J. Hovson
 Reg. Book. Year. Month.
 Tonnage { Net 1784 Built at Glasgow When built 1875 11
 Gross 2811
 Under Dk. 2737 By whom built Napier Owners J. Burns & Co.
 Port belonging to London Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greens BK
 (State Name of Dock.)

Last Survey, No. 40422 Port of Iron Linn

Classed 100 A 7.80

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	<u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	<u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	<u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	<u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	<u>"</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	<u>"</u>
Topsides <u>"</u>	Ceiling <u>"</u>	<u>"</u>
Wales <u>"</u>	Rudder <u>"</u>	<u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. Coated When put on <u>new</u>	<u>"</u>
Engine Room Skylights <u>Good</u>	Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>
Cargo and Main Hatchways <u>Good</u> Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. Bottom & counter Chain cable range in the Government Survey inspection. I have been examined by me 300 fathoms in all. She is now in an efficient state and eligible to remain as classed. The special fee not been paid for SS No. 1.

Committee's Minute Friday, October, 14th 18 81,

Senhouse Martindale

Character assigned 100 A 7.80

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Year. Month.
 Tonnage { Net Built at When built
 Gross
 Under Dk. By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of

Classed

Present Condition of the Decks <u> </u>	Treenails <u> </u>	<u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	<u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	<u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	<u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	<u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	<u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	<u> </u>
Topsides <u> </u>	Ceiling <u> </u>	<u> </u>
Wales <u> </u>	Rudder <u> </u>	<u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. When put on <u> </u>	<u> </u>
Engine Room Skylights <u> </u>	Coal Bunkers, Openings, Lids, &c. <u> </u>	Scuppers <u> </u>
Cargo and Main Hatchways <u> </u> Hatches <u> </u>		

General Observations, Opinion as to Class, &c.

Committee's Minute 18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON667-0009

