

# ANNUAL SURVEYS.

40932

No. \_\_\_\_\_ Survey held at London Date, first Survey 21<sup>st</sup> Oct. Last Survey 22<sup>nd</sup> Oct. 18 87  
 No. in on the S.S. "Plessey" Master M. Scott  
 Reg. Book. 472 Net 1121 Built at Blyth When built 1881 3  
 Tonnage Gross 1752 Under Dk. 1654 By whom built Hodgkin & Sons Owners Thos. Ward & Co.  
 Port belonging to London Destined Voyage Ibrail  
 If Surveyed Afloat or in Dry Dock Union Dry Dock (State Name of Dock.)

Last Survey, No. 15371 Port of Novo Classed 100 A. 1.  
 Present Condition of the Decks Good Treenails Good Rivets Good  
 Waterways do Breasthooks and Stemson do  
 Comings do Transoms, Pointers, and Crutches do  
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do  
 Lower Deck Beams & Fastenings do Ditto ditto at other places do  
 Planksheers do Keelsons do  
 Sheerstrakes do Clamps and Shelves do  
 Topsides do Ceiling do  
 Wales do Rudder do  
 Plank (Bottom) and Counter do Copper or Y.M. — When put on —  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers do Cargo and Main Hatchways Good Hatches do  
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.

Bottom cleaned and coated, and steering gear repaired.

This Vessel is in good condition, and eligible to remain as classed.


Committee's Minute Fri. 14 Oct. 1887 Joseph Thomson  
 Character assigned 100 A. 1. Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) — Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18 \_\_\_\_\_  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Under Dk. \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_ (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the Decks \_\_\_\_\_  
 Waterways \_\_\_\_\_ Treenails \_\_\_\_\_  
 Comings \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Topsides \_\_\_\_\_ Clamps and Shelves \_\_\_\_\_  
 Wales \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Rudder \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 (If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.

Committee's Minute 18  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) — Paid 18

W0667-0077



© 2021

Lloyd's Register Foundation