

40932
Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 25/10/87)

No. in
Reg. Book.

Survey held at London

Date, first Survey and

Last Survey Oct. 24th 1881

472 on the Machinery of the S.S. "Masset"

(Number of Visits 1)

Tonnage, Gross 1754

Built at Blyth

When built 1881

Ditto, Net 1121

Owners Watts & Ward & Co.

Port belonging to London

Diameter of Cylinder 32" & 60"

Engines made by Blair & Co.

When made 1881

Length of Stroke 39"

Boilers made by Ditto

When made 1881

Pressure of Steam 80 lbs.

If Surveyed Afloat or in Dry Dock Union Dock
(State name of Dock.)

Classed 100A1

Registered Horse Power 140

Last Survey No.

Port

Lloyds M.C. 4.81

Particulars of Repairs and Examination

For Annual Survey -

(State cause of Repairs.)
Vessel placed in dry dock, sea connections examined
& found to be in good condition. Propeller & its con-
nections found to be sound & the tail shaft a good
working fit in Stern Bush.

General Observations, Opinion, and Recommendation:— As far as seen this
vessel appears eligible to remain as classed

Entry or Registering Fee... £ : :
(per Section 27.)

Survey Fee (per Section 28) ... £ : : received by me,

Certificate (if required) ... £ : : 188

to be sent as per margin.


(Travelling Expenses, if any, £)

Committee's Minute

Friday, Oct. 28th 1881

Assigned

Geo. E. Milnerison.
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

LDN667-0078

It is submitted that this
vessel is eligible to remain
as chartered.

or I

25/10/81



© 2021

Lloyd's Register
Foundation