

ANNUAL SURVEYS.

40947

(Received at London Office, 1. 11. 81.)

No. _____ Survey held at London Date, first Survey 19th Oct^r Last Survey 22nd Oct^r 1881
 No. in on the B^g Kingdom of Sweden Master W. C. Smith
 Reg. Book. 180 Net 788 Built at Sunderland When built 1875 Year. _____ Month. _____
 Tonnage Gross 830 Under Dk. 727 By whom built Mounsey & Foster Owners Gosman & Smith
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock Paplan dry Dock (State Name of Dock.)

Last Survey, No. 28483 Port of Lyon Classed 100 A1 12-80
 Present Condition of the Decks Good Rivets Good
 Waterways _____ Breasthooks and Stems _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Hull (Bottom) and Counter _____ Copper or Y.M. _____ When put on _____
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____
 (If a Steam Ship, state if a Report is also sent on the Machinery _____)
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned and painted. Rudder pintles re-bushed.
This vessel is now in good and efficient condition and in our opinion eligible to remain as classed.
 Charles Edwards
 Wm. C. Davey
 Surveyors to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at London Date, first Survey 21st Oct^r Last Survey 24th Oct^r 1881
 No. in on the S. Lammernoor Master J. W. Guthrie
 Reg. Book. 172 Net 1626 Built at Port Glasgow When built 1874 Year. _____ Month. _____
 Tonnage Gross 1710 Under Dk. 1535 By whom built J. Reid & Co. Owners Williamson Milligan & Co.
 Port belonging to Liverpool Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock West India dry dock (State Name of Dock.)

Last Survey, No. 39970 Port of Lon Classed 100 A1 12-80
 Present Condition of the Decks Good Rivets Good
 Waterways _____ Breasthooks and Stems _____
 Comings _____ Transoms, Pointers, and Crutches _____
 Upper Deck Beams & Fastenings _____ Timbers of the Frame at the Openings _____
 Lower Deck Beams & Fastenings _____ Ditto ditto at other places _____
 Planksheers _____ Keelsons _____
 Sheerstrakes _____ Clamps and Shelves _____
 Topsides _____ Ceiling _____
 Wales _____ Rudder _____
 Hull (Bottom) and Counter _____ Copper or Y.M. Cement When put on 1874
 Engine Room Skylights _____ Coal Bunkers, Openings, Lids, &c. _____ Scuppers _____
 (If a Steam Ship, state if a Report is also sent on the Machinery _____)
 General Observations, Opinion as to Class, &c. _____

Bottom cleaned and painted.
This vessel is now in good and efficient condition and eligible in our opinion to remain as classed.
 Charles Edwards
 Wm. C. Davey
 Surveyors to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

LON 667-0096

The Surveyors are requested not to write on or in the space...

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

Lloyd's Register Foundation