

ANNUAL SURVEYS.

41093

(Received at London Office)

Survey held at London Date, first Survey Nov 30th Last Survey Dec 1st 1881
 in on the SS Viking Master R. J. J. J.
 Book. 37 Net 1686 Built at Glasgow When built 1874 Year. 6 Month.
 Tonnage Gross 2588 By whom built _____ Owners W. Ross & Co
 Under Dk. 1753 Port belonging to Glasgow Destined Voyage Glasgow
 If Surveyed Afloat or in Dry Dock Victoria Dock afloat
(State Name of Dock.)

[Handwritten Signature]

Last Survey, No. 40742 Port of London Classed 100A 8.81
 Character in Register Book. SS Lon No. 1.75

Present Condition of the Decks	<u>Good</u>	Treenails <u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stenson	"	Windlass and Capstan
Comings	"	Transoms, Pointers, and Crutches	"	Pumps
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	Boats
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	Masts, Yards, &c. <u>new Main Boom</u>
Planksheers	"	Keelsons	"	Condition, how ascertained
Sheerstrakes	"	Clamps and Shelves	"	Sails
Topsides	"	Ceiling	"	Anchors, No. of <u>3 Nos. 12 & 14</u>
Wales	"	Rudder	"	Cables <u>Part on 12</u>
Plank (Bottom) and Counter	"	Copper or Y.M. <u>✓</u> When put on <u>✓</u>	"	Hawsers and Warps
Engine Room Skylights <u>Good</u>		Caulking of Bottom, Deck, & Waterways	<u>Good</u>	Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. <u>Good</u>		Scuppers <u>Good</u>		Cargo and Main Hatchways
Hatches <u>Good</u>				

General Observations, Opinion as to Class, &c. owing to damage Part of Main & Bridge House Decks caulked, two New Boats & two ditto repaired, new Main Boom, Main & Bridge Deck House Rails repaired with other sundry repairs on deck &c.
She is now in an efficient state and eligible to remain as classed.
Damage fee £2-2-0

Committee's Minute Friday, January 26th, 1882. Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the Reg. Book. _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 Gross _____ By whom built _____ Owners _____
 Under Dk. _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
 Character in Register Book. _____

Present Condition of the Decks		Treenails		
Waterways		Breasthooks and Stenson		Windlass and Capstan
Comings		Transoms, Pointers, and Crutches		Pumps
Upper Deck Beams & Fastenings		Timbers of the Frame at the Openings		Boats
Lower Deck Beams & Fastenings		Ditto ditto at other places		Masts, Yards, &c.
Planksheers		Keelsons		Condition, how ascertained
Sheerstrakes		Clamps and Shelves		Sails
Topsides		Ceiling		Anchors, No. of
Wales		Rudder		Cables
Plank (Bottom) and Counter		Copper or Y.M. _____ When put on _____		Hawsers and Warps
Engine Room Skylights _____		Caulking of Bottom, Deck, & Waterways		Standing and Running Rigging
Coal Bunkers, Openings, Lids, &c. _____		Scuppers _____		Cargo and Main Hatchways
Hatches _____				

General Observations, Opinion as to Class, &c. _____

Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



Surveys are requested...

Insert Character precisely as in Register Book.

Insert Character precisely as in Register Book.

W. King

AMNUAL SURVEYS



© 2021

Lloyd's Register
Foundation