

ANNUAL SURVEYS.

4 11 05

(Received at London Office *Friday, January 1. 1882*)

No. 1120 on the SS Compton Survey held at London Date, first Survey Jan 24 Last Survey Jan 6 1882
 Reg. Book. 1120 Master J J Eggers
 Tonnage { Net 1186 Built at Newcastle When built 1878
 { Gross 1804
 { Under Dk. 1746 By whom built W Richardson & Co Owners W Milburn & Co
 Port belonging to London Destined Voyage Cardiff
 If Surveyed Afloat or in Dry Dock Thames & N. Dry Dock
(State Name of Dock.)

Last Survey, No. X 170 Port of Copenhagen Classed 100 A. 7.81
Years assigned. Character in Register Book.

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	Rivets <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Windlass and Capstan <u>Good</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Pumps <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Boats <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Masts, Yards, &c. <u>"</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Condition, how ascertained <u>From Stk</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Sails <u>Good</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Anchors, No. of <u>3 Avo. 2 1/2 Redgs</u>
Wales <u>"</u>	Rudder <u>"</u>	Cables <u>Part on Stk</u> <u>Good</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Covered</u> When put on <u>Mar</u>	Hawsers and Warps <u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Standing and Running Rigging <u>"</u>
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>"</u>	Cargo and Main Hatchways <u>"</u>
Hatches <u>"</u>		

General Observations, Opinion as to Class, &c. A Bower anchor supplied 29-3-15 tested to 28-12-20 rather than proving horse dated April 2nd 1881 signed E Sedhouse Assistant Superintendent.
The above named anchor was put on when about to sail, the other 2 Bowers appeared larger but the marks & weights being on the underside could not be seen. She is in an efficient state and respectfully recommend her to remain as classed. one stem plate renewed through damage by the anchor

Committee's Minute Tuesday, January 24th. 1882.
 Character assigned 100 A
 Surveyor to Lloyd's Register of British and Foreign Shipping. Sedhouse Martindale
 Certificate (if required, to be sent as per margin) Paid 18

No. _____ Survey held at _____ Date, first Survey _____ Last Survey _____ 18____
 No. in on the Reg. Book. _____ Master _____
 Tonnage { Net _____ Built at _____ When built _____
 { Gross _____
 { Under Dk. _____ By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____
(State Name of Dock.)

Last Survey, No. _____ Port of _____ Classed _____
Years assigned. Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. _____
 Committee's Minute _____ 18____
 Character assigned _____
 Surveyor to Lloyd's Register of British and Foreign Shipping. _____
 Certificate (if required, to be sent as per margin) Paid 18

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 5 for Annual Survey, when there are no repairs.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)



LONG667-0301

Compton

10/10/1911

ANNUAL SURVEYS



© 2021

Lloyd's Register
Foundation