

ANNUAL SURVEYS.

41241

(Received at London Office, Tuesday, March, 7th, 1882.)

No. 453 Survey held at London Date, first Survey July 11 Last Survey March 3 1882
 No. in on the 5 Glendarnel Master J. Poe 3 Wants
 Reg. Book. 453 Net 1761 Built at Glasgow When built 1876 1 Month
 Tonnage Gross 1840 Under Dk. 167.5 By whom built Barclay Owners J. A. Allan
 Port belonging to Glasgow Destined Voyage Sydney
 If Surveyed Afloat or in Dry Dock Blackwall Pt Dry Dock & Afloat
(State Name of Dock.)

Insert Character precisely as in Register Book.

Last Survey, No. 194 Port of Man Classed 100A1-4.81
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson "
 Comings " Transoms, Pointers, and Crutches " Windlass and Capstan Good
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Pumps "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Boats "
 Planksheers " Keelsons " Masts, Yards, &c. "
 Sheerstrakes " Clamps and Shelves " Condition, how ascertained From St
 Topsides " Ceiling " Sails Good
 Wales " Rudder " Anchors, No. of 3 Nos. St & Rudder
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new Cables Part on St Good
 Caulking of Bottom, Deck, & Waterways Good Standing and Running Rigging "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom ke coated

She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, March, 10th, 1882. Samuel Martin
 Character assigned 100A1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 159 Survey held at London Date, first Survey July 6 Last Survey July 28 1882
 No. in on the 5 Tantallon Castle Master J. Currie
 Reg. Book. 159 Net 1057 Built at Greenock When built 1865 3 Month
 Tonnage Gross 1057 Under Dk. 98.5 By whom built R. Steel Owners J. Currie & Co
 Port belonging to Liverpool Destined Voyage Cape
 If Surveyed Afloat or in Dry Dock Greenock & Afloat
(State Name of Dock.)

Insert Character precisely as in Register Book.

Last Survey, No. 402.33 Port of Low Classed 7A 7 3.81
 Present Condition of the Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stemson " Windlass and Capstan Good
 Comings " Transoms, Pointers, and Crutches " Pumps "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings " Boats "
 Lower Deck Beams & Fastenings " Ditto ditto at other places " Masts, Yards, &c. "
 Planksheers " Keelsons " Condition, how ascertained From St
 Sheerstrakes " Clamps and Shelves " Sails Good
 Topsides " Ceiling " Anchors, No. of 3 Nos. St & Rudder
 Wales " Rudder Brushed Cables Part on St Good
 Plank (Bottom) and Counter " Copper or Y.M. Coated When put on new Standing and Running Rigging "
 Caulking of Bottom, Deck, & Waterways Good Hatches "
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers Good Cargo and Main Hatchways Good

Bottom ke coated, one Port New plate removed damaged by an anchor, top fallant fore-castle plate fixed. She is now in an efficient state and eligible to remain as classed.

Committee's Minute Friday, March, 10th, 1882. Samuel Martin
 Character assigned 7A 1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



The Surveyors are requested not to write on or below the space for Committee's Minute.