

## ANNUAL SURVEYS.

(Received at London Office, RECEIVED 23rd, MAR. 82)

No. 173 Survey held at London Date, first Survey March 6 Last Survey March 22 1882  
No. in on the S Candida Master Matthewson  
Reg. Book. 173 Net 1222 Built at Whitehaven When built 1875 Year. 5 Month. 3  
Tonnage Gross 1275 By whom built White & Co Owners London & Export  
Under Dk. 1181 Port belonging to Liverpool Destined Voyage Australia  
If Surveyed Afloat or in Dry Dock Greenwich by Mr. [unclear]  
(State Name of Dock.)

Last Survey, No. 27553 Port of SeaClassed 100A. 5.81  
Years assigned. 58 Character in Register Book. See [unclear]

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	"	
Comings	"	Transoms, Pointers, and Crutches	"	"	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	
Planksheers	"	Keelsons	"	"	
Sheerstrakes	"	Clamps and Shelves	"	"	
Topsides	"	Ceiling	"	"	
Wales	"	Rudder	"	"	
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Canted</u> When put on <u>new</u>			
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>		
Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches	"

General Observations, Opinion as to Class, &amp;c.

Bottom is coated.  
She is now in an efficient state and eligible to remain as classed

Committee's Minute Friday, March 24th. 1882.Character assigned 100A. 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

No. 526 Survey held at London Date, first Survey March 4 Last Survey March 14 1882  
No. in on the BN Ellora Master Phillips  
Reg. Book. 526 Net 1125 Built at Glasgow When built 1876 Year. 5 Month. 5  
Tonnage Gross 1186 By whom built Barelay Owners Foley & Co  
Under Dk. 1056 Port belonging to London Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock Blackwall by Mr. [unclear]  
(State Name of Dock.)

Last Survey, No. 40369 Port of SeaClassed 100A. 5.81  
Years assigned. 58 Character in Register Book. See [unclear]

Present Condition of the

Decks	<u>Good</u>	Treenails	<u>Rivets</u>	<u>Good</u>	
Waterways	"	Breasthooks and Stemson	"	"	
Comings	"	Transoms, Pointers, and Crutches	"	"	
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the Openings	"	"	
Lower Deck Beams & Fastenings	"	Ditto ditto at other places	"	"	
Planksheers	"	Keelsons	"	"	
Sheerstrakes	"	Clamps and Shelves	"	"	
Topsides	"	Ceiling	"	"	
Wales	"	Rudder	"	"	
Plank (Bottom) and Counter	"	Copper or Y.M. <u>Canted</u> When put on <u>new</u>			
Engine Room Skylights		Caulking of			
Coal Bunkers, Openings, Lids, &c.		Bottom, Deck, & Waterways	<u>Good</u>		
Scuppers	<u>Good</u>	Cargo and Main Hatchways	<u>Good</u>	Hatches	"

General Observations, Opinion as to Class, &amp;c.

Bottom is coated  
She is now in an efficient state and eligible to remain as classed

Committee's Minute Friday, March 24th. 1882.Character assigned 100A. 1

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 18

LON667-0521