

Report of Survey for Repairs of Engines and Boilers.

41298

No. _____ (Received at London Office, 28. 2. 82)
 No. in Reg. Book. Survey held at London Date, first Survey and Last Survey 9. 2 1882

157 on the Machinery of the S. S. Edith (Number of Visits 1)

Tonnage, Gross	<u>89</u>	Built at	<u>Berwick</u>	When built	<u>1878</u>
Ditto, Net	<u>53</u>	Owners	<u>W. Hudson</u>	Port belonging to	<u>London</u>
Diameter of Cylinder	<u>12</u>	Engines made by	<u>Wardhaugh & Bulmer</u>	When made	<u>1878</u>
Length of Stroke	<u>16</u>	Boilers made by		When made	<u>1878</u>
Pressure of Steam	<u>60</u>	If Surveyed Afloat or in Dry Dock	<u>Fountain Dry Dock</u>	Classed	<u>11</u>
Registered Horse Power	<u>20</u>	(State name of Dock.)		Years assigned	<u>11</u>
Last Survey No.		Port		Character in Register Book	<u>A 1</u>
					<u>5.78</u>
					<u>Lloyds M.C. 478</u>

Particulars of Repairs and Examination Annual.
 (State cause of Repairs.)
Examined sea chests & connections & found them in good condition

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel appears eligible to remain as classed

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ : : received by me,
 Certificate (if required) ... £ : : 188 }
 to be sent as per margin.

Ch. Bromeyer
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Tuesday, March, 28th 1882.

Assigned



LON667-0539

The Ship, and subsequent Repairs and Examinations, to be carried out, (Condition of Engr. (The Surveyors are requested not to write on or before the space for Committee's Minute).

Insert Character Precisely as in the Register Book.

This submitted to Mr. [unclear]
need is subject
to [unclear] as shown
M. [unclear]



© 2021

Lloyd's Register
Foundation