

41477
Report of Survey for Repairs of Engines and Boilers.

No. _____
Reg. Book. _____
Survey held at London Date, first Survey _____ and Last Survey Apr. 25th 1882
(Received at London Office, 16.6.82)
506 on the Machinery of the S S "Gleuway" (Number of Visits 1)
Tonnage, Gross 2159 Built at Glasgow When built 1871
Ditto, Net 1411 Owners M^c Gregor Low & Co. Port belonging to Glasgow
Diameter of Cylinder 40" + 70" Engines made by Lon. & Glas. Co. When made 1871
Length of Stroke 42" Boilers made by _____ When made 1879
Pressure of Steam 75 lbs. If Surveyed Afloat or in Dry Dock Glen's Dry Dock (State name of Dock.)
Registered Horse Power 250 Classified 100A1
Last Survey No. _____ Port Lloyds M.C. 12.79

Particulars of Repairs and Examination For Annual Survey.
(State cause of Repairs.)

Vessel placed in dry dock sea connections examined & found to be in good condition Tail shaft down 1/2 in Stern Bush. Four new blades have been fitted to loss of propeller.

General Observations, Opinion, and Recommendation:— As far as seen this vessel is eligible in my opinion to remain as classed.

Entry or Registering Fee... £ : :
(per Section 27.)
Survey Fee (per Section 28) ... £ : : received by me,
Certificate (if required) ... £ : : 188
to be sent as per margin.
(Travelling Expenses, if any, £)

Geo. E. Wilkinson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Friday, 19th May, 1882.

Assigned



Lloyd's Register
Foundation

Report of Survey for Repairs of Engines and Boilers.

It is submitted that this vessel is eligible to remain as blessed.

W. S.

16 | 5 | 82

© 2021

Lloyd's Register
Foundation