

15/82 *Damage Repairs* 41492  
**REPORT of SURVEY for REPAIRS, &c.**

(Received at London Office, 23/5/82)

No. *London* Date, first Survey *April 13<sup>th</sup>* Last Survey *May 19<sup>th</sup>* 1882  
 No. in Survey held at Reg. Book. *325* on the *S Thyatira (Composite)* Master *C Lawrence*

TONNAGE under Tonnage Deck *899*  
 Ditto of Spar Deck, or Avning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Deck  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage *962*  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam *962*  
 Engine Room  
 Reg. Tons as S<sup>r</sup>mer, cut on Bm.

Built at *Aberdeen* When built *1867*  
 Owners *G Thompson & Co* Port belonging to *Aberdeen*  
 Residence  
 By whom built *Hood* Destined Voyage *Australia*  
 If Surveyed Afloat or in Dry Dock *East India St*  
(State Name of Dock)

Length of Poop *ft.* Ditto, Forecastle *ft.* Ditto, Raised Quarter Deck *ft.*  
 Years assigned. *19 A 5.81*  
 Character in Register Book. *SS Lon 81. 377 Lon 77.*

Last Survey, No. *40444* Port *London*  
 REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.  
*At present owing to damage.  
 New outer stem or facing piece from the light mast  
 up to lower part of buttwate banked oak. New bowsprit,  
 jibboom. Fore top gallant Mast. Fore topmast yard & fore yard repaired.*

Present Condition of the					
Decks	<i>Good</i>	Treenails	<i>Good</i>	Windlass and Capstan	<i>Good</i>
Waterways	"	Bolts	"	Pumps	"
Comings	"	Breasthooks and Stenson	"	Boats	"
Upper Deck Beams & Fastenings	"	Transoms, Pointers, and Crutches	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Condition, how ascertained	<i>Examined</i>
Planksheers	"	Ditto Ditto at other places	"	Sails	<i>Good</i>
Sheerstrakes	"	Keelsons	"	Anchors No. of <i>3 Nos. 11 &amp; Kedys</i>	"
Topsides	"	Clamps and Shelves	"	Cables <i>Part on St</i>	<i>Good</i>
Wales	"	Ceiling	"	Hawsers and Warps	"
Plank (Bottom) and Counter	"	Rudder	"	Standing & Running Rigging	"
Engine Room Skylights	"	Copper (or Y.M.) <i>Y Metal When put on 1881</i>	"	Cargo and Main Hatchways	<i>Good</i>
Coal Bunker, Openings, Lids, &c.	"	Caulking of	"	Hatches	"
Scuppers	<i>Good</i>	Bottom, Deck, & Waterways	<i>Good</i>		

General Observations, Opinion as to Class, &c.  
*She is now in an efficient state and eligible to remain as classed.*

The Amount of Entry Fee ... £ ... received by me, *CYR*  
*27/5/82* Special ... £ *1* : *1* : *30/5/1882*

Certificate (if required) to be sent as per margin... } £ : *5* : "  
 (Travelling Expenses, if any, £ )  
 Committee's Minute *Friday, 26th May, 1882.*

Character assigned *19 A*  
*JTW*  
 ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.  
 © 2021 Lloyd's Register Foundation LON668-0155

(If a Steam Ship, state if a Report is also sent on the Machinery.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (Form No. 2 for Repairs, 1,000-19/6/81.)

(Insert Character precisely as in Register Book.)