

REPORT of SURVEY for REPAIRS, &c.

41543

(Received at London Office, 1.5.82)

No. in Survey held at London Date, first Survey 18th Apr Last Survey 25th Apr 1882
 Reg. Book. 467 on the Iron S.S. "Petrel" Master G. Taylor
 Tonnage under Tonnage Deck 694 YEAR. MONTH. 12
 Ditto of Spar Deck, or Awning Deck Built at Aberdeen When built 1876
 Ditto of Poop Owners Genl Messrs Co Port belonging to London
 Ditto of Raised Qr. Dk. Residence
 Ditto of Houses on Deck By whom built Hall Russell & Co Destined Voyage Lisbon
 Ditto of Fe. & St. 841 If Surveyed Afloat or in Dry Dock Genl Messrs Co's dry Dock & Afloat
 Gross Tonnage Reg. Tons as St' mer, but on Bm. 540 (State Name of Dock)
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.
 Last Survey, No. 37238 ~~25829~~ Port London Classed 100 A1
 REPAIRS, OR EXAMINATION AS PER RULE 100 A1 2.80

Cause of Repairs to be clearly stated.

In fore hold ceiling equal to 2 strakes removed on each side
 ceiling removed from top of tanks. Tanks cleaned out and
 examined - also tested as per Rule. Plating cleaned and
 repainted, one plate of bottom on Starboard side taken out
 repaired and replaced. Chain Cables cauped at bottom
 recoated

Present Condition of the Decks	Good	Freenails	Good	Windlass and Capstan	Good
Waterways	--	Rivets	--	Pumps	4 ho
Comings	--	Breasthooks and Stenson	--	Boats	3 ho
Upper Deck Beams & Fastenings	--	Transoms, Pointers, and Crutches	--	Masts, Yards, &c.	--
Lower Deck Beams & Fastenings	--	Timbers of the Frame at the openings	--	Condition, how ascertained	Examined
Planksheers	--	Ditto Ditto at other places	--	Sails	Good
Sheerstrakes	--	Keelsons	--	Anchors	No. of 3 B. 18 + 2 K
Topsides	--	Clamps and Shelves	--	Cables	240 fms
Wales	--	Ceiling	--	Hawsers and Warps	6 ho
Plank (Bottom) and Counter	--	Rudder	--	Standing & Running Rigging	--
Engine Room Skylights	Good	Copper (on rudder) <u>Cement</u> When put on <u>1876</u>	Good	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	Hatches	Good

General Observations, Opinion as to Class, &c.

She is now in good condition eligible to con-
 tinue as classed and marked S.S. No 1 in the Register
 Book

The Amount of Entry Fee ... £ 3 : 3 : - received by me, } F.F.E.
 9/6/82 Special ... £ 3 : 3 : - } 29/8/1882 }
 Certificate (if required) } £ : 5 : 0
 to be sent as per margin... }

(Travelling Expenses, if any, £)

Committee's Minute

Friday, 9th June, 1882.

Character assigned

Lloyd's Reg 5.02

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.



© 2021

Lloyd's Register Foundation

LN668-0254

If a Steam Ship, state if a Report is also sent on the Machinery

Form No. 2 for Repairs, -4,000-13/6/81.

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.