

# Report of Survey for Repairs of Engines and Boilers.

No.

(Received at London Office, 1882)

No. in Reg. Book. Survey held at *London*

Date, first Survey *May 8<sup>th</sup>* Last Survey *June 2<sup>nd</sup>* 1882.

*773* on the Machinery of the *S. S. "Ananda"*

(Number of Visits *10*)

Tonnage, Gross *357*

Built at *Grunwick*

When built *1871*

Ditto, Net *222*

Owners *Burma S. N. Co.*

Port belonging to *Grunwick*

Diameter of Cylinder *20" & 33"*

Engines made by *Carr & Co*

When made *1871*

Length of Stroke *30"*

Boilers made by *Ditto*

When made *1871*

Pressure of Steam *45 lbs.*

If Surveyed Afloat or in Dry Dock *Pontoon & Aft*  
(State name of Dock.)

Classed *90A-*

Registered Horse Power *60*

Last Survey No.

Port

## Particulars of Repairs and Examination For Annual Survey

(State cause of Repairs.)

Vessel placed on Pontoon, sea connections examined & found to be in good condition. Propeller & its connections sound & tail shaft a good fit in Stern bush. Examined cylinders, Slides, & valve faces, found to be in good condition. Crank shaft in good condition. Thrust bearing lined up. There being no discharge valves to any of the pipes leading through ship's side, recommended that these should be fitted, & return valves to suction pipes to Fore & After holds. All the lead suction pipes & some of the discharge pipes from bilge pumps found to be in a defective state, recommended that these pipes be renewed & repaired as required.

Boiler examined, backs of combustion chambers found to be more or less buckled as also the tops, & stays had been fitted in the crowns at some former time. Several stays found to have been leaking at backs of combustion chambers, 15 new stays have been fitted. Shell of boiler found fairly good.

On visiting the vessel on 2<sup>nd</sup> June was told by owners representative that it had been decided not to reclass her.

General Observations, Opinion, and Recommendation:—

Entry or Registering Fee... £

Survey Fee (per Section 28) ... £

Certificate (if required) ... £

Travelling Expenses, if any, £

Received by me,

188

*Geo. E. Wilson*

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Con

Assigned

Friday, 9<sup>th</sup> June, 1882

*B. D. M. H. H.*



Lloyd's Register Foundation

LONG68-0282



It is submitted that as the owners  
have declined to carry out the  
Surveyors recommendations to enable  
the vessel to continue her  
class her character should  
be withdrawn from the Society's  
Register Book

DP

5/6/82.



© 2021

Lloyd's Register  
Foundation