

REPORT of SURVEY for REPAIRS, &c.

No. 69 on the Ship, "Wanganui" Date, first Survey 21st June Last Survey 20th June 1882
Reg. Book. 69 on the Ship, "Wanganui" Master Watt
TONNAGE under Tonnage Deck 884 XXX
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage 1136
Crew Space, as per Rule
Register Tonnage, cut on Beam 1077 XXX
Engine Room
Reg. Tons as St' mer, cut on Bm.

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. 100 A.1
Last Survey, No. 40588 Port London
REPAIRS, OR EXAMINATION AS PER RULE To complete S.S. No. 1.
Cause of Repairs to be clearly stated.

The vessel placed in dry docks on blocks.
The timber boards and ceiling on each side removed
and both surfaces of outside plating examined
where required to complete the survey see Mr.
Congdon's report of survey. London No. 40588.
The masts spars, and general equipment examined.

Present Condition of the
Decks Good
Waterways
Comings
Upper Deck Beams & Fastenings
Lower Deck Beams & Fastenings
Planksheers
Sheerstrakes
Topsides
Wales
Plank (Bottom) and Counter
Engine Room Skylights Coal Bunker, Openings, Lids, &c. Scuppers
General Observations, Opinion as to Class, &c. This vessel is in good and efficient
Condition and eligible in the opinion to remain
as classed, and noted in the Register Book.
S. S. London. No. 1. & 2.

The Amount of Entry Fee ... £ 2 : 2 : 0 received by me, 12/7/82
Certificate (if required) to be sent as per margin... £ 5 : -
(Travelling Expenses, if any, £)
Committee's Minute Tuesday, 4th July 1882.
Character assigned 100 A.1
Surveyor to Lloyd's Register of British and Foreign Shipping.
© 2021 Lloyd's Register Foundation
LON 668-0339