

ANNUAL SURVEYS.

41034c

No. Survey held at London Date, first Survey June 19th Last Survey June 19th 1882
(Received at London Office, 24/6/82)
 No. in on the SS Scotland Master Lackhurst
Reg. Book. 245 (No. of Visits 1)
 Tonnage Net 1654 Built at Linghorn When built 1869 Year. Month.
Gross 2645 By whom built J Key Owners Temperley, Carter & Sanks
Under Dk. 1705 Port belonging to London Destined Voyage Liverpool, Glasgow, & Australia
 If Surveyed Afloat or in Dry Dock Royal Albert Dry Dock (State Name of Dock.)

Last Survey, No. 41278 Port of Low
 Present Condition of the Decks Good Treenails Good Rivets Good
 Waterways Good Breasthooks and Stemson Good
 Comings Good Transoms, Pointers, and Crutches Good
 Upper Deck Beams & Fastenings Good Timbers of the Frame at the Openings Good
 Lower Deck Beams & Fastenings Good Ditto ditto at other places Good
 Planksheers Good Keelsons Good
 Sheerstrakes Good Clamps and Shelves Good
 Topsides Good Ceiling Good
 Wales Good Rudder Good
 Plank (Bottom) and Counter Good Copper or Y.M. Boated When put on now
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches Good
 General Observations, Opinion as to Class, &c. She is now in an efficient state and eligible to remain as classed.

Classed 100A 282
SS Low No. 3. 82
Years assigned. Character in Register Book.


The Surveyors are requested not to write on or below the space for Committee's Minute.

Committee's Minute Tuesday, 15th July, 1882. Senhouse Martindale
 Character assigned 100A Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) TRM Paid 18

No. Survey held at Date, first Survey Last Survey 18
(No. of Visits)
 No. in on the Master
Reg. Book. (No. of Visits)
 Tonnage Net Built at When built Year. Month.
Gross By whom built Owners
Under Dk. Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock (State Name of Dock.)

Last Survey, No. Port of Classed
Years assigned. Character in Register Book.
 Present Condition of the Decks Treenails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shelves
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



LONG63-0437