

41660 Jan.

forward on port side renewed. Pumps lifted, examined and refitted, Cathhead on port side new of English Oak,

Raised quarter deck doubled with $1\frac{3}{4}$ Yellow Pine.

Fore yard new new, Running and standing rigging refitted with part new, and the lanyards all new.

The deck house refitted, the boat new and 1 d^o repaired. The decks and waterways caulked throughout. The cement in the bottom repaired where necessary, and the ceiling taken up for examination, ^{replaced} with part new.

The Windlass unhooked and wood linings sufficiently stripped for examination, and the Chain Cables ranged and found complete. A small Kedge is found to be on board weighing ^{cut 925 lbs} 1. 2. 7 ex stock and stock ^{cut 1000 lbs} 2. 3 N^o 11075. ^{with regard to certificate attached.} see letter from ^{owners} attached.

1 Forebail, 2 Lower Topsails, 2 Upper Topsails, 1 Mizzen Staysail, 1 Jib, & 1 Fore Topmast Staysail new.

J. W. Miles



© 2021

Lloyd's Register
Foundation