

ANNUAL SURVEYS.

No. 76 Survey held at London Date, first Survey July 18 Last Survey Aug 2 1882
 No. in Reg. Book. on the Iron Ship "Barn" Master Cutting
 Tonnage { Net 1650 Built at Sunderland When built 1875 Month. 7
 Gross 1719
 Under Dk. 1567 By whom built Howard Owners J. House
 Port belonging to London Destined Voyage Africa
 If Surveyed Afloat or in Dry Dock Agent dock and H.I. Dock
 (State Name of Dock.)

Last Survey, No. 27465 Port of London Classed 100 A.1
 Present Condition of the Decks ford Treenails Amits ford 10 Licks 100. 7. 80
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches ford
 Upper Deck Beams & Fastenings ford Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers none Keelsons do
 Sheerstrakes do Clamps and Shelves Amits ford
 Topsides do Ceiling ford
 Wales do Rudder ford
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways ford
 Coal Bunkers, Openings, Lids, &c. ford Scuppers ford Cargo and Main Hatchways ford Hatches ford
 General Observations, Opinion as to Class, &c. How done, the bottom cleaned and renovated. Sudden lifted and further bushed. Being now in good & efficient condition the vessel is eligible to remain as classed.

Committee's Minute Friday, 15 August, 18 82.
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 139 Survey held at London Date, first Survey July 21 Last Survey Aug 2 1883
 No. in Reg. Book. on the Iron Ship "Walthamstow" Master Sherris
 Tonnage { Net 1057 Built at Port Margate When built 1865 Month. 2
 Gross 1057
 Under Dk. 989 By whom built A. Duncan & Co Owners James Shields Lewis & Co
 Port belonging to Liverpool Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock North Commercial Dock, and West India Dock
 (State Name of Dock.)

Last Survey, No. 3320 Port of PLY. Classed 100 A.1
 Present Condition of the Decks ford Treenails Amits ford 10 Licks 100. 7. 80
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches ford
 Upper Deck Beams & Fastenings ford Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers none Keelsons do
 Sheerstrakes do Clamps and Shelves Amits ford
 Topsides do Ceiling ford
 Wales do Rudder do
 Plank (Bottom) and Counter do Copper or Y.M. do When put on do
 Engine Room Skylights do Caulking of Bottom, Deck, & Waterways ford
 Coal Bunkers, Openings, Lids, &c. do Scuppers ford Cargo and Main Hatchways ford Hatches ford
 General Observations, Opinion as to Class, &c. How done, the bottom scraped and renovated. The sudden lifted and further bushed. Now in good & efficient condition the vessel is eligible to remain as classed.

Committee's Minute Friday, 14th August, 18 82.
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18