

# ANNUAL SURVEYS.

No. *76* Survey held at *London* Date, first Survey *July 18* Last Survey *Aug 2* 18*82*  
 No. in Reg. Book. on the *Iron Ship "Barn"* Master *Cutting*  
 Tonnage { Net *1650* Built at *Sunderland* When built *1875* Month. *7*  
 Gross *1719*  
 Under Dk. *1587* By whom built *Howard* Owners *J. House*  
 Port belonging to *London* Destined Voyage *Africa*  
 If Surveyed Afloat *or* in Dry Dock *Agent dock and H.I. Dock*  
 (State Name of Dock.)

Last Survey, No. *27465* Port of *London* Classed *100 A.1*  
 Present Condition of the Decks *ford* Treenails *Amits* *ford* 10 Links 100. 7. 80  
 Waterways *do* Breasthooks and Stemson *do*  
 Comings *do* Transoms, Pointers, and Crutches *ford*  
 Upper Deck Beams & Fastenings *ford* Timbers of the Frame at the Openings *do*  
 Lower Deck Beams & Fastenings *do* Ditto ditto at other places *do*  
 Planksheers *none* Keelsons *do*  
 Sheerstrakes *do* Clamps and Shelves *Amits* *ford*  
 Topsides *do* Ceiling *ford*  
 Wales *do* Rudder *ford*  
 Plank (Bottom) and Counter *do* Copper or Y.M. *do* When put on *do*  
 Engine Room Skylights *do* Caulking of Bottom, Deck, & Waterways *ford*  
 Coal Bunkers, Openings, Lids, &c. *ford* Scuppers *ford* Cargo and Main Hatchways *ford* Hatches *ford*  
 General Observations, Opinion as to Class, &c. *How done, the bottom cleaned and renovated. Sudden lifted and further bushed. Being now in good & efficient condition than I expect to be able to say of any other ship in the class.*

Committee's Minute *Friday, 15 August, 18 82.*  
 Character assigned *100 A.1* Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. *139* Survey held at *London* Date, first Survey *July 21* Last Survey *Aug 2* 18*83*  
 No. in Reg. Book. on the *Iron Ship "Walthamstow"* Master *Sherris*  
 Tonnage { Net *1057* Built at *Port Margate* When built *1865* Month. *2*  
 Gross *1057*  
 Under Dk. *989* By whom built *H. Dorman & Co* Owners *James Shields Lewis & Co*  
 Port belonging to *Liverpool* Destined Voyage *New Zealand*  
 If Surveyed Afloat *or* in Dry Dock *North Commercial Dock, and West India Dock*  
 (State Name of Dock.)

Last Survey, No. *3320* Port of *PLY.* Classed *100 A.1*  
 Present Condition of the Decks *ford* Treenails *Amits* *ford* 10 Links 100. 7. 80  
 Waterways *do* Breasthooks and Stemson *do*  
 Comings *do* Transoms, Pointers, and Crutches *ford*  
 Upper Deck Beams & Fastenings *ford* Timbers of the Frame at the Openings *do*  
 Lower Deck Beams & Fastenings *do* Ditto ditto at other places *do*  
 Planksheers *none* Keelsons *do*  
 Sheerstrakes *do* Clamps and Shelves *Amits* *ford*  
 Topsides *do* Ceiling *ford*  
 Wales *do* Rudder *do*  
 Plank (Bottom) and Counter *do* Copper or Y.M. *do* When put on *do*  
 Engine Room Skylights *do* Caulking of Bottom, Deck, & Waterways *ford*  
 Coal Bunkers, Openings, Lids, &c. *do* Scuppers *ford* Cargo and Main Hatchways *ford* Hatches *ford*  
 General Observations, Opinion as to Class, &c. *How done, the bottom scraped and renovated. The sudden lifted and further bushed. Now in good & efficient condition than I expect to be able to say of any other ship in the class.*

Committee's Minute *Friday, 14th August, 18 82.*  
 Character assigned *100 A.1* Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18