

ANNUAL SURVEYS.

No. Survey held at London Date, first Survey 11 July Last Survey July 14th 18 82
 No. in on the SS Tanfield Master J. Bowdell
 Reg. Book. 50 Tonnage 482 Built at Newcastle When built 1864 12
 By whom built Palmer Bros Owners J. Fenwick & Son
 Port belonging to London Destined Voyage Syne (Coal Trade)
 If Surveyed Afloat or in Dry Dock Pontoon Victoria Dock

Last Survey, No. 40495 Port of Lon

Present Condition of the Decks <u>Good</u>	Treenails <u>Rivets</u> <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>From Str</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3 Nos. 12 & 18 lbs</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Pack on deck</u> <u>Good</u>
Wales <u>"</u>	Rudder <u>Brushed</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Coated</u> When put on <u>Mon</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	Cargo and Main Hatchways <u>Good</u> Hatches <u>"</u>
General Observations, Opinion as to Class, &c. <u>Bottom be coated, a few keel rivets renewed.</u>		

She is now in an efficient state and eligible to remain as classed.

She has made 40 voyages from the Syne to London with Coals this year.

Committee's Minute Friday, 8th September, 1882.
 Character assigned A 1

Senhouse Martindale
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in on the Master
 Reg. Book. Tonnage Built at When built
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock

Last Survey, No. Port of Classed

Present Condition of the Decks <u> </u>	Treenails <u> </u>	Windlass and Capstan <u> </u>
Waterways <u> </u>	Breasthooks and Stemson <u> </u>	Pumps <u> </u>
Comings <u> </u>	Transoms, Pointers, and Crutches <u> </u>	Boats <u> </u>
Upper Deck Beams & Fastenings <u> </u>	Timbers of the Frame at the Openings <u> </u>	Masts, Yards, &c. <u> </u>
Lower Deck Beams & Fastenings <u> </u>	Ditto ditto at other places <u> </u>	Condition, how ascertained <u> </u>
Planksheers <u> </u>	Keelsons <u> </u>	Sails <u> </u>
Sheerstrakes <u> </u>	Clamps and Shelves <u> </u>	Anchors, No. of <u> </u>
Topsides <u> </u>	Ceiling <u> </u>	Cables <u> </u>
Wales <u> </u>	Rudder <u> </u>	Hawsers and Warps <u> </u>
Plank (Bottom) and Counter <u> </u>	Copper or Y.M. <u> </u> When put on <u> </u>	Standing and Running Rigging <u> </u>
Engine Room Skylights <u> </u>	Caulking of Bottom, Deck, & Waterways <u> </u>	Cargo and Main Hatchways <u> </u> Hatches <u> </u>
General Observations, Opinion as to Class, &c. <u> </u>		

Committee's Minute 18
 Character assigned

 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required) Paid 18
 Lloyd's Register Foundation