

ANNUAL SURVEYS.

41737

No. 153 Survey held at London Date, first Survey 29 Aug 82 Last Survey 4 Sep 82 1882

No. in on the SS Samuel Laing Master Wm Knight
 Reg. Book. 153 Tonnage { Net 477 Built at Newcastle When built 1854
 Gross 609 By whom built Palmer Bros Owners J Fenwick & Son
 Under Dk. 572 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St
 (State Name of Dock.)

Last Survey, No. 40346 Port of London Classed 80 A 4.81
SS Lon No 2.81
SS No 3.75

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Canted When put on now
 Caulking of Good
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom be canted.

She is now in an efficient state
and eligible to remain as afloat.
All lining on Portside of Windlass stripped off & examined. After end of Nail clamps.

Committee's Minute Tuesday, 19th September, 1882 Senhouse Martindale

Character assigned 80 A 4.81 TRW Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. 153 Survey held at London Date, first Survey 29 Aug 82 Last Survey 4 Sep 82 1882

No. in on the SS Samuel Laing Master Wm Knight
 Reg. Book. 153 Tonnage { Net 477 Built at Newcastle When built 1854
 Gross 609 By whom built Palmer Bros Owners J Fenwick & Son
 Under Dk. 572 Port belonging to London Destined Voyage Coal Trade
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St
 (State Name of Dock.)


Last Survey, No. 40346 Port of London Classed 80 A 4.81
SS Lon No 2.81
SS No 3.75

Present Condition of the
 Decks Good Treenails Rivets Good
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Canted When put on now
 Caulking of Good
 Bottom, Deck, & Waterways Good
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "
 General Observations, Opinion as to Class, &c. Bottom be canted.

Committee's Minute 18

Character assigned 80 A 4.81 TRW

Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18



Form No. 3 for Annual Survey, to be filled up by the Surveyor, and sent to the Registrar of Shipping, with the Report.

Insert Character precisely as in Register Book.

LON 669-0012