

Report of Survey for Repairs of Engines and Boilers.

No. 1281 (Received at London Tuesday, 26th September, 1882)
 No. in Reg. Book. 1281 Survey held at London Date, first Survey 1 Sept Last Survey 12 Sep 1882
 on the Machinery of the S. S. "Avena" (Number of Visits 3)
 Tonnage, Gross 429 Built at Liverpool When built 1873
 Ditto, Net 459 Owners W. Flaherty Port belonging to Uddvalla
 Diameter of Cylinder 24 48 Engines made by Onseburn Eng Works When made 1873
 Length of Stroke 33 Boilers made by Onseburn Eng Works When made 1873
 Pressure of Steam 65 lb If Surveyed Afloat or in Dry Dock Commercial Dry Years assigned. 9021
 Registered Horse Power 95 (State name of Dock.) & floating OK. Character in Register Book. 9.81
 Last Survey No. MS. 9.80, BS. 481 Port MS. 9.80, BS. 481

Particulars of Repairs and Examination

Special Survey No.

Examined Boiler and found it to be in a good condition

Examined Safety Valves (weighted lever) slide valves Cylinders and pumps & found them in a good condition

Examined Crankshafts & found it in a good condition

Vessel placed in dry dock sea connections examined & found to be in good condition. Propeller & its connections found to be sound & the stern bush worn 1/8"

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and the vessel is in our opinion fit to have the notification B & MS 9.82. recorded in the Register Book.

Entry or Registering Fee... £ 4 : 4 : 0
 Survey Fee (per Section 28) ... £ 4 : 4 : 0
 Certificate (if required) ... £ 2 : 0 : 0
 to be sent as per margin.
 (Travelling Expenses, if any, £ 0 : 0 : 0)

received by me, H. J. Brown 16th Oct 1882

Geo. E. Harrison

C. E. Brown

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Friday, 29th September, 1882

Assigned



© 2021

Lloyd's Register Foundation

(State if Report is also sent on the Hull of the Ship)

(Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

Insert Character precisely as in the Register Book.

LA 2669-0069

His submittal that this vessel
is eligible to have the
notification BMS 9.82
recorded the boiler being
subject to annual
survey as per Rules

M 25/9/82



© 2021

Lloyd's Register
Foundation