

# ANNUAL SURVEYS.

41786

(Received at London Office, 23 9 82 th)  
 Date, first Survey August 28<sup>th</sup> Last Survey September 27 1882

No. \_\_\_\_\_ Survey held at London Date, first Survey August 28<sup>th</sup> Last Survey September 27 1882  
 No. in on the Iron B-12 Kingdom of Sweden Master Alfred Cooper  
 Reg. Book. 160 Net 788 Built at Sunderland When built 1875 - 4 Month.  
 Tonnage { Gross 830 Under Dk. 427 By whom built Mounsey & Foster Owners Gosman & Smith  
 Port belonging to London Destined Voyage Madras  
 If Surveyed Afloat or in Dry Dock Poplar dry Dock and Afloat  
(State Name of Dock.)

Last Survey, No. 40947 Port of London Classed S.S. Low No 1-79 Character in Register Book. 100 A 1  
 Present Condition of the Decks good Treennails Rivets good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shelves stringers "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1875  
 Caulking of Bottom, Deck, & Waterways good  
 Engine Room Skylights " Coal Bunkers, Openings, Lids, &c. " Scuppers good Cargo and Main Hatchways good Hatches good  
(If a Steam Ship, state if a Report is also sent on the Machinery.....)  
 General Observations, Opinion as to Class, &c.

*This vessel has now been placed in dry Dock, the bottom cleaned and examined and recoated with Paint. The following new sails were put on board, viz 1 Foresail, 1 Lower topsail, 1 Oppoballant sail, 1 Royal, 1 Spanker, 1 Mizzen staysail, 1 upper Mizzen staysail & 1 standing jib. It is now in good and efficient condition and eligible in my opinion to remain as classed.*  
 Committee's Minute Friday, 29th September, 1882.

Character assigned 100 A 1 J.B.W.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin) Paid 30<sup>th</sup> 1882

The Surveyors are requested not to write on or below the space for Committee's Minute.

Insert Character precisely as in Register Book.

LON 669 0080