

ANNUAL SURVEYS.

41811

No.

Survey held at

London

Date, first Survey

18 Sept

Last Survey

18 82

No. in
Reg. Book.

232

on the

SS Eldorado

Master

(No. of Visits)

Stevenson

Year.

Month.

Tonnage

Net

2157

Built at

Ibuck

When built

1873

3

Gross

3332

Under Dk.

2128

By whom built

Charles & Co

Owners

A Gray & E S Sawes

Port belonging to

Glasgow

Destined Voyage

Calcutta.

If Surveyed Afloat or in Dry Dock

Albert Dry Dock

(State Name of Dock.)

Last Survey, No.

41570

Port of

Lon.

Classed

Years assigned.

Character in Register Book.

100A-582

SS Lon 114-2, 81

Present Condition of the

Decks

Good

Treenails

Good

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams & Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shelves

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or Y.M.

When put on

Engine Room Skylights

Good

Coal Bunkers, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

General Observations, Opinion as to Class, &c.

Bottom be coated.

She is now in an efficient state and eligible to remain as classed.

Committee's Minute

Friday, 10th October, 18 82.

Surveyor to Lloyd's Register of British and Foreign Shipping.

Character assigned

100A-582

Certificate (if required, to be sent as per margin)

Paid 18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in
Reg. Book.

on the

Master

(No. of Visits)

Year.

Month.

Tonnage

Net

Built at

When built

Gross

Under Dk.

By whom built

Owners

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Waterways

Breasthooks and Stemson

Comings

Transoms, Pointers, and Crutches

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Lower Deck Beams & Fastenings

Ditto ditto at other places

Planksheers

Keelsons

Sheerstrakes

Clamps and Shelves

Topsides

Ceiling

Wales

Rudder

Plank (Bottom) and Counter

Copper or Y.M.

When put on

Engine Room Skylights

Good

Coal Bunkers, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

General Observations, Opinion as to Class, &c.

Bottom be coated.

Committee's Minute


18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid 18



© 2021

Lloyd's Register

Foundation

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

100669-0108

(If a Steam Ship, state if a Report is also sent on the Machinery.)

(If a Steam Ship, state if a Report is also sent on the Machinery.)

100-26/4/82.

(The Surveyors are requested not to write on or below the space for Committee's Minute.)