


Report of Survey for Repairs of Engines and Boilers.

No. 41819  
Reg. Book. (Received at London Office RECEIVED 20th SEP. 82.)  
Survey held at London Date, first Survey 5 Sep Last Survey 7 Sep 1882  
on the Machinery of the S. S. "Blower" (Number of Visits 2)  
Tonnage, Gross 949 Built at Lunderland When built 1875  
Ditto, Net 601 Owners General Steam Navigation Co Port belonging to London  
Diameter of Cylinder 28 52 Engines made by M. & L. Marine Co When made 1875  
Length of Stroke 33 Boilers made by                      When made 1875  
Pressure of Steam 65 If Surveyed Afloat or in Dry Dock Deptford Green Dock Classed 100A1  
Registered Horse Power 110 (State name of Dock.)                      Years assigned 11. 81  
Last Survey No.                      Port L. M. C. 180

Particulars of Repairs and Examination Annual and Damage  
(State cause of Repairs.)  
Examined sea-cocks & connections & found them  
in a good condition.  
The propeller has been removed and new lignum vitae  
fitted to the Stern tube & propeller replaced.  
Examined Boiler and found it to be in a good con-  
dition. Safety valves in good condition.

General Observations, Opinion, and Recommendation:— As far as seen the  
machinery appears to be in a safe working condition  
and is in my opinion eligible to have the notification  
B.S. 9. 82 recorded in the Register Book

Entry or Registering Fee... £ - : - : -  
Survey Fee (per Section 28) ... £ 1 : 1 : } received by me, }                       
Certificate (if required) ... £ - : 2 : } 1st Sep 1882 }                       
(Travelling Expenses, if any, £                     )  
Committee's Minute Tuesday, 10th October, 1882.  
Assigned B.S. 9. 82  


The submitter that this vessel  
is eligible to have the  
notification PS 9.82  
recorded, the holder being  
subject to recovery as  
per Hull

M 18/9/82



© 2021

Lloyd's Register  
Foundation