

Report of Survey for Repairs of Engines and Boilers.

No.

No. in
Reg. Book.

Survey held at

London Case

Date, first Survey

Last Survey

188

on the Machinery of the

S. S. "Mula"

(Number of Visits

Year

Tonnage, Gross

Built at

When built

"Ditto, Net

Owners

Port belonging to

Year

Diameter of Cylinder

Engines made by

When made

Year

Length of Stroke

Boilers made by

When made

Pressure Steam

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

*Classed

Years
assigned.

Character in Register Book.

Power

No.

56

Port

Mka

Particulars of Repairs and Examination

(State cause of Repairs.)

See Report

Observations, Opinion, and Recommendation :—

Entry or Registering Fee... £

(per Section 27.)

Survey Fee (per Section 28) ... £

Certificate (if required)
to be sent as per margin.

(Travelling Expenses, if any, £

received by me,


188

Committee's Minute

188

Assigned

Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



Lloyd's Register
Foundation

Classing Committee
3 Nov 1882

~~At~~ ^{3/81} ~~am~~ ^{now}
with limits as suggested
by the Chief Registrar
permanently 2/11/82



© 2021

Lloyd's Register
Foundation