

Change of owners 41931

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, 12. 10. 82)

No. in Survey held at London Date, first Survey 21 Sept Last Survey 28 Oct 1882
 Reg. Book. (No. of Visits 5)
 on the SS Godalming Master not given yet asked for
 TONNAGE under Tonnage Deck 1038 YEAR. MONTH. 6
 Ditto of Spar Deck, or Awning Deck Built at Sunderland When built 1881
 Ditto of Poop Owners The Godalming Steam Navigation Co Ltd Port belonging to London
 Ditto of Raised Qr. Dk. Spurston & Co Ltd Superattached
 Ditto of Houses on Deck Owners The Godalming Steam Navigation Co Ltd
 Ditto of Forecastle Residence
 Gross Tonnage 1292 By whom built Blumer & Co Destined Voyage Belize
 Crew Space, as per Rule
 Register Tonnage, cut on Beam
 Engine Room
 Reg. Tons as St' mer, cut on Bm. 834 If Surveyed Afloat or in Dry Dock Greens Bay, etc
 (State Name of Dock)
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft. Years assigned. Character in Register Book.

Last Survey, No. 4824 Port Ham Classed 100A 482
 REPAIRS, OR EXAMINATION AS PER RULE
 Cause of Repairs to be clearly stated.

At present the wood ceiling taken off
 the top of double bottom and the plates scraped
 and coated with boiled wood tar (Stockholm) and
 cement. Several butts on both sides of flat of bottom
 caulked. Some of the slanting pillars in the hold
 have been put perpendicular so as wood barges can
 be well stowed. Bottom & coated,
 ceiling relaid on double bottom

Names of ownership put in 9/10/82

Present Condition of the	God	Treenails	Rivets	God	Windlass and Capstan	God
Decks	God	Breasthooks and Stenson	God	Pumps	"	"
Waterways	"	Transoms, Pointers, and Crutches	"	Boats	"	"
Comings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c.	"	"
Upper Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained	From BH	"
Lower Deck Beams & Fastenings	"	Keelsons	"	Sails	God	"
Stanchions	"	Clamps and Shelves	"	Anchors No. of & Bcs	82 & Redips	"
Strakes	"	Ceiling	"	Cables	Part on BH	God
Planks	"	Rudder	"	Hawsers and Warps	"	"
Plank (Bottom) and Counter	"	Copper (on Y.M.)	Boiled When put on	Standing & Running Rigging	"	"
Engine Room Skylights	God	Caulking of	Bottom, Deck, & Waterways	God	Cargo and Main Hatchways	God
Coal Bunker, Openings, Lids, &c.	God	Scuppers	God	Hatches	"	"

General Observations, Opinion as to Class, &c.
 She is now in an efficient state and eligible to remain as classed

The Amount of Entry Fee ... £ 1 : - : } received by me, Y.Y.E.
 Special ... £ 1 : 1 : } 15-12-1882
 Certificate (if required) }
 to be sent as per margin... } £ : :
 (Travelling Expenses, if any, £)

Surveyor to Lloyd's Register of British and Foreign Shipping.
Leadbrough Martindale

Committee's Minute Tuesday, 21. December, 1882.
 Character assigned 100A
T.B.W.

Form No. 2 for Repairs—4,000—20/5/82.
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

LON 669-0243

