

ANNUAL SURVEYS.

41938

No. 1353 Survey held at London Date, first Survey October 4 Last Survey November 8 1882
 No. in Reg. Book. 1353 on the Iron Bth "Crownthorpe" Master H. R. Everett
 Tonnage Net 812 Built at Sunderland When built 1873 - 9
 Gross 847 Under Dk. 741 By whom built R. Thompson & Co. Owners Livingston Briggs & Co.
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock West India dry Dock and Afloat
 (State Name of Dock.)

Last Survey, No. 40913 Port of London Classed 100 A 1
 Present Condition of the
 Decks good Treanails Rivets good S.S. Law N^o 2-81 10, 81
 Waterways " Breasthooks and Stenson "
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves Stringers "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1873
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps "
 Boats 4 "
 Masts, Yards, &c. "
 Condition, how ascertained by observation
 Sails Sufficient
 Anchors, No. of 3 B, 1 S & 2 H
 Cables part seen on deck good
 Hawkers and Warps sufficient
 Standing and Running Rigging "

Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock the bottom examined and recoated with Paint. The hatches, in the ceiling of the flat equal to 8 shakes on each side, lifted for the purpose of cleaning out the drainage from a cargo of sperm oil, the cement & floors &c. examined and found good. She is now in good and efficient condition and eligible to remain as classed.
 Committee's Minute Tuesday, 21st November, 18 82.
 Character assigned 100 A 1 TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) — Paid 18

No. 614 Survey held at London Date, first Survey October 11 Last Survey November 10 1882
 No. in Reg. Book. 614 on the Iron Bth "Atataura" Master Greenstreet
 Tonnage Net 853 Built at Glasgow When built 1868 - 12
 Gross 898 Under Dk. 841 By whom built Hicken & Maunsell Owners New Zealand Ship^g Co. Ltd.
 Port belonging to Littleton N.Z. Destined Voyage Auckland
 If Surveyed Afloat or in Dry Dock Canal dry Dock and Afloat
 (State Name of Dock.)

Last Survey, No. 40997 Port of London Classed * A 1
 Present Condition of the
 Decks good Treanails Rivets good S.S. Law N^o 3-78 12, 81
 Waterways " Breasthooks and Stenson " S.S. Law N^o 1-81
 Comings " Transoms, Pointers, and Crutches "
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "
 Lower Deck Beams & Fastenings " Ditto ditto at other places "
 Planksheers " Keelsons "
 Sheerstrakes " Clamps and Shelves Stringers "
 Topsides " Ceiling "
 Wales " Rudder "
 Plank (Bottom) and Counter " Copper or Y.M. Cemented When put on 1868
 Caulking of Bottom, Deck, & Waterways good
 Windlass and Capstan good
 Pumps "
 Boats "
 Masts, Yards, &c. "
 Condition, how ascertained by observation
 Sails Sufficient & good
 Anchors, No. of 3 B, 1 S & 2 H
 Cables part seen on deck good
 Hawkers and Warps sufficient
 Standing and Running Rigging sufficient

Engine Room Skylights — Coal Bunkers, Openings, Lids, &c. — Scuppers good Cargo and Main Hatchways good Hatches good
 (If a Steam Ship, state if a Report is also sent on the Machinery)
 General Observations, Opinion as to Class, &c. This vessel has now been placed in dry dock, the bottom examined and recoated with Paint. She is in good and efficient condition and eligible in my opinion to remain as classed.
 Committee's Minute Tuesday, 21st November, 18 82.
 Character assigned * A 1 TRW
 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) — Paid 18

(The Surveyors are requested not to write on or below the space for Committee's Minute.)
 (Form No. 1 for Annual Survey, when there are no repairs. 4000-6/12/80.)
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)
 (Insert Character precisely as in Register Book.)
 102669-0253