

# Report of Survey for Repairs of Engines and Boilers.

41952

No. \_\_\_\_\_ (Received at London Office, 23. 11. 82)  
 No. in Reg. Book. Survey held at London Date, first Survey 31<sup>st</sup> Oct Last Survey 7 Nov 1882  
968 on the Machinery of the P. S. Monarch (Number of Visits 4)  
 Tonnage, Gross 2316 Built at Middlesbro' When built 1878  
 Ditto, Net 1522 Owners Macintyre B & Co Port belonging to Newcastle  
 Diameter of Cylinder 38 71 Engines made by Blair & Co When made 1878  
 Length of Stroke 45 Boilers made by \_\_\_\_\_ When made 1878  
 Pressure of Steam 78  
 Registered Horse Power 280 If Surveyed Afloat or in Dry Dock Blackwall Point (State name of Dock.) W. Dock & Millwall Dock Years assigned. 100A1 Character in Register Book. 3. 82  
 Last Survey No. \_\_\_\_\_ Port L. M. C. 9. 78

Particulars of Repairs and Examination Special Survey No 1  
 (State cause of Repairs.)

Examined Seacocks & connections and found them in a good condition  
Examined Boilers and found them in a good condition  
Examined Safety valves, slide valves cylinders and pumps and found them in a good condition  
The crankshaft was found to be in a good condition  
The safety valves were found to be set at 70 lbs per square inch.

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and is in my opinion eligible to have the notification L.M.C 11.82 recorded in the Register Book

Entry or Registering Fee... £ 1 : 10 : -  
 Survey Fee (per Section 28) ... £ 4 : 4 : - received by me, } 448  
 Certificate (if required) ... £ : : 4. 12. 1882  
 to be sent as per margin.  
 (Travelling Expenses, if any, £ \_\_\_\_\_)

Committee's Minute Friday, 24th November, 1882.  
 Assigned L M C 11. 02

*Ordnance Survey Report*  
4/11/83  
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.



[Form No. 9-3000, 20/5/82.] (The Surveyors are requested not to write on or below the space for Committee's Minute.) (Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.) (State of Report is also sent on the Hull of the Ship.)

Insert Character precisely as in the Register Book.

L02669-0273

It is submitted that this vessel  
is eligible to have the certificate  
S.M.C. 11.82 recorded the  
vessel being subject to  
survey as per Rule

M. 21/1/82

21/1/82  
The vessel is eligible to have the certificate  
S.M.C. 11.82 recorded the vessel being subject to  
survey as per Rule

1st part of the certificate  
is not valid unless the vessel is  
subject to survey as per Rule  
11.82 of the Merchant Shipping  
Act 1994. The vessel is not  
subject to survey as per Rule  
11.82 of the Merchant Shipping  
Act 1994.

1st part of the certificate  
is not valid unless the vessel is  
subject to survey as per Rule  
11.82 of the Merchant Shipping  
Act 1994. The vessel is not  
subject to survey as per Rule  
11.82 of the Merchant Shipping  
Act 1994.



Register of Survey for Boilers of Engines and Boilers