

12/12/82

ANNUAL SURVEYS.

42042

No.

Survey held at

London

Date, first Survey

9 Dec

(Received at London Office,

Last Survey

13.12.82

1882

No. in
Reg. Book.

on the

SS Bothwell Castle

Master

(No. of Visits)

Thomson

Tonnage

Net 1658

Built at

Middlesboro

When built

1881

Month.

Gross 2542

Under Dk. 2355

By whom built

R. Gexendo

Owners

J. Skinner & Co

Port belonging to

London

Destined Voyage

Antwerp

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Albert by St

Last Survey, No.

201

Port of

Shi

Classed

Years assigned.

100 A. 82

Character in Register Book.

8. 82

Present Condition of the

Decks

Good

Treenails

Drives

Good

Waterways

Breasthooks and Stemson

Good

Comings

Transoms, Pointers, and Crutches

Good

Upper Deck Beams & Fastenings

Timbers of the Frame at the Openings

Good

Lower Deck Beams & Fastenings

Ditto ditto at other places

Good

Planksheers

Keelsons

Good

Sheerstrakes

Clamps and Shelves

Good

Topsides

Ceiling

Good

Wales

Rudder

Good

Plank (Bottom) and Counter

Copper or Y.M. Banded

When put on

Good

Engine Room Skylights

Good

Coal Bunkers, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

General Observations, Opinion as to Class, &c.

Bottom &c. coated

She is now in an efficient state
and eligible to remain as classed.

Committee's Minute

Wednesday 27th December, 1882.

Character assigned

Good

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

No.

Survey held at

Date, first Survey

Last Survey

18

No. in
Reg. Book.

on the

Master

(No. of Visits)

Year.

Month.

Tonnage

Net

Built at

When built

Gross

By whom built

Owners

Under Dk.

Port belonging to

Destined Voyage

If Surveyed Afloat or in Dry Dock

(State Name of Dock.)

Last Survey, No.

Port of

Classed

Years assigned.

Character in Register Book.

Present Condition of the

Decks

Treenails

Breasthooks and Stemson

Windlass and Capstan

Waterways

Transoms, Pointers, and Crutches

Pumps

Comings

Timbers of the Frame at the Openings

Boats

Upper Deck Beams & Fastenings

Ditto ditto at other places

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Keelsons

Condition, how ascertained

Planksheers

Clamps and Shelves

Sails

Sheerstrakes

Ceiling

Anchors, No. of

Topsides

Rudder

Cables

Wales

Copper or Y.M.

When put on

Hawsers and Warps

Plank (Bottom) and Counter

Caulking of
Bottom, Deck, & Waterways

Standing and Running Rigging

Engine Room Skylights

Coal Bunkers, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

General Observations, Opinion as to Class, &c.

Committee's Minute

18

Character assigned

Surveyor to Lloyd's Register of British and Foreign Shipping.

Certificate (if required, to be sent as per margin)

Paid

18

(If a Steam Ship, state if a Report is also sent on the Machinery)


(If a Steam Ship, state if a Report is also sent on the Machinery)

(Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/82.)

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

LON 669-0379



© 2021

Lloyd's Register Foundation