

# REPORT of SURVEY for REPAIRS, &c.

42133

(Received at London Office, 22. 1. 83)

in Survey held at London Date, first Survey 2<sup>nd</sup> Jan<sup>y</sup> Last Survey 8<sup>th</sup> Jan<sup>y</sup> 1883  
 Book. 27 on the S.S. "Mid Survey" (No. of Visits)  
 Master G. Dobbyn  
 Tonnage under Tonnage Deck 885  
 Ditto of Spar Deck, or Avning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 903  
 Net Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons a. 566 566  
 Length of I. ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.  
 No. 41400 Port Lon  
 Examinations as per Rule  
 Repairs to be clearly stated.  
 Built at Newcastle When built 1870 YEAR. MONTH. 4  
 Owners Harris & Dixon Port belonging to London  
 Residence  
 By whom built Palmer's Co Destined Voyage Coasting  
 If Surveyed Afloat or in Dry Dock Limetkiln dry Dk  
 (State Name of Dock)  
 Years assigned. Character in Register Book.  
 Classed GOA 1 4.82  
S.S. Lon no. 3-79  
 Society's Load-Line (if assigned) as painted on Ship  
 Society's Freeboard (if assigned) as painted on Ship

Through Damage -  
 One plate taken off rolled and refitted and 2 straightened in place - on Port side, also 3 plates of the side of Bridge House taken off refitted, one bulwark plate new & one straightened in place. 3 Beam frames scarp'd. one new piece of main Rail, fitting of House made good. Bottom recoated

Present Condition of the Decks	Good	Greenails Ropes	Good	Windlass and Capstan	Good
Waterways	--	Breasthooks and Stenson	--	Pumps	--
Comings	--	Transoms, Pointers, and Crutches	--	Boats	--
Upper Deck Beams & Fastenings	--	Timbers of the Frame at the openings	--	Masts, Yards, &c.	--
Lower Deck Beams & Fastenings	--	Ditto Ditto at other places	--	Condition, how ascertained	from Deck
Planksheers	--	Keelsons	--	Sails	Good
Sheerstrakes	--	Clamps and Shells	--	Anchor No. of 3 B. 15 & 2 K	
Topsides	--	Ceiling	--	Cables	part seen Good
Wales	--	Rudder	--	Hawsers and Warps	--
Plank (Bottom) and Counter	--	Copper (or Y.M.) When put on	--	Standing & Running Rigging	--
Engine Room Skylights	Good	(State if on Felt.)		Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Cement (if Iron Ship) 1870		Hatches	Good
General Observations, Opinion as to Class, &c.		Caulking of Bottom, Deck, & Waterways	Good		

She is now in good condition and eligible to continue as Classed

Wm. C. Davey  
 John H Heck

The Amount of Entry Fee ... £ 10 : 10 : 0 received by me, 25/1/83 Special ... £ 1 : 1 : 0

Surveyor to Lloyd's Register of British and Foreign Shipping.

Committee's Minute  
 Character assigned  
 Friday, 26th January, 1883.  
 GOA 1



Insert Character precisely as in Register Book.

LON 669-0503