

ANNUAL SURVEYS.

No. 5 Survey held at London Date, first Survey 18th Jan Last Survey 27th Jan 1883
 No. in Reg. Book. on the Iron Barque "Quathlamba." Master W. Melville
 Tonnage 467 Net 495 Gross 450 Under Dk. Built at Aberdeen When built 1879 Month 2nd
 By whom built A. Hall & Co Owners J. T. Rennie & Son
 Port belonging to Aberdeen Destined Voyage Port Natal
 If Surveyed Afloat or in Dry Dock In the Upper Globe Dry Dock.
 (State Name of Dock.)


Last Survey, No. 41151 Port of Lon Classed 100 A.1.
 Present Condition of the Decks good Treennails good Rivets good
 Waterways do Breasthooks and Stemson do
 Comings do Transoms, Pointers, and Crutches do
 Upper Deck Beams & Fastenings do Timbers of the Frame at the Openings do
 Lower Deck Beams & Fastenings do Ditto ditto at other places do
 Planksheers do Keelsons do
 Sheerstrakes do Clamps and Shells do
 Topsides do Ceiling do
 Wales do Rudder do
 Plating (Bottom) and Counter do Copper or Y.M. When put on do
 Caulking of Bottom, Deck, & Waterways good
 Engine Room Skylights do Coal Bunkers, Openings, Lids, &c. do Scuppers good Cargo and Main Hatchways good Hatches good
 General Observations, Opinion as to Class, &c. The bottom has been examined and coated. The fore topgallant yard and the main royal yard renewed. The special survey No. 1 is due this year but the Owners desire to defer it until she comes back again to England which is expected to be by the end of the year. This vessel is in good and efficient condition & eligible in my opinion to remain as classed.

Committee's Minute Frids, 2nd January, 1883. J. H. Truscott.
 Character assigned 100 A.1 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid 18

No. Survey held at Date, first Survey Last Survey 18
 No. in Reg. Book. on the Master
 Tonnage Net Gross Under Dk. Built at When built Year. Month.
 By whom built Owners
 Port belonging to Destined Voyage
 If Surveyed Afloat or in Dry Dock
 (State Name of Dock.)

Last Survey, No. Port of Classed
 Present Condition of the Decks Treennails
 Waterways Breasthooks and Stemson
 Comings Transoms, Pointers, and Crutches
 Upper Deck Beams & Fastenings Timbers of the Frame at the Openings
 Lower Deck Beams & Fastenings Ditto ditto at other places
 Planksheers Keelsons
 Sheerstrakes Clamps and Shells
 Topsides Ceiling
 Wales Rudder
 Plank (Bottom) and Counter Copper or Y.M. When put on
 Caulking of Bottom, Deck, & Waterways
 Engine Room Skylights Coal Bunkers, Openings, Lids, &c. Scuppers Cargo and Main Hatchways Hatches
 General Observations, Opinion as to Class, &c.

Committee's Minute 18
 Character assigned Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) Paid



© 2021

Lloyd's Register Foundation

(Insert Character precisely as in Register Book.)

(Insert Character precisely as in Register Book.)

450-0544