

# REPORT of SURVEY for REPAIRS, &c.

42188

No. 822 on the Steel S.S. Lydian Monarch Master Huggitt

No. in Survey held at London Date, first Survey October 23/82 Last Survey January 25 1883

Reg. Book. 822 on the Steel S.S. Lydian Monarch Master Huggitt

TONNAGE under Tonnage Deck 2855 Built at Dumbarton When built 1881 - 5

Ditto of Spar Deck, or Awning Deck  
Ditto of Poop  
Ditto of Raised Qr. Dk.  
Ditto of Houses on Deck  
Gross Tonnage 3916 Owners Royal Exchange Shipping Co Port belonging to London

Residence London By whom built A. McMillan & Co Destined Voyage Alexandria

Engine Room  
Reg. Tons as St' mer, cut on Bm. 2546 If Surveyed Afloat or in Dry Dock James Iron Works & Dock of Afloat

Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

has 3 Decks (2 steel) & Shelter Deck Last Survey, No. 41493 Port London Classed 100A1

REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated. Society's Load-Line (if assigned) as painted on Ship Load line 23 ft 6 in 5, 82

Society's Freeboard (if assigned) as painted on Ship


This vessel has now been placed in dry Dock the bottom examined and recoated with Paint. The Shelter deck has been reworked where found necessary, and the Chain Cables ranged for Government Surveyors inspection, examined and found 300 fathoms. A Flying Bridge has been erected Amidships, and Lloyd's Load Line is painted on the Sides.

Present Condition of the Decks	Good	Presents	Plants	Good	Windlass and Capstan	Good
Waterways	"	Breasthooks and Stenson	"	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	"	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	"	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	"	Condition, how ascertained by Observation	"
Planksheers	"	Keelsons	"	"	Sails	Sufficient
Sheerstrakes	"	Clamps and Shelves	Stringers	"	Anchors	No. of 3 B, 1 S & 2 H
Topsides	"	Ceiling	"	"	Cables	ranged 300 fathoms
Wales	"	Rudder	"	"	Hawsers and Warps	Sufficient
Plank (Bottom) and Counter	"	Copper (or Y.M.) When put on	"	"	Standing & Running Rigging	"
Engine Room Skylights	Good	Cement (if used on Ship) Cemented 1881	"	"	Cargo and Main Hatchways	Good
Coal Bunker, Openings, Lids, &c.	Good	Caulking of Bottom, Deck, & Waterways	Good	"	Hatches	Good
General Observations, Opinion as to Class, &c.	<p>This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.</p>					

The Amount of Entry Fee ... £ : : received by me, )  
Special ... £ : : 188 )  
Certificate (if required) } £ : :  
to be sent as per margin... }

(Travelling Expenses, if any, £ )  
Committee's Minute Tuesday 6th February, 1883.  
Character assigned 100A1

*J. W. Miles*  
Surveyor to Lloyd's Register of British and Foreign Shipping.



If a Steam Ship, state whether or not a Report is also sent on the Machinery

Insert Character precisely as in Register Book.

LON 669-0564