

# REPORT of SURVEY for REPAIRS, &c.

in Survey held at London Date, first Survey January 20 Last Survey January 26 1883  
Book. 58 on the Iron S.S. Lord of the Isles (No. of Visits) 4 Master J. C. Kelgate  
Tonnage under Tonnage Deck 2440 Built at Glasgow When built 1870 — 6  
Ditto of Spar Deck, or Avoning Deck Owners Shaw Bushby & Co Port belonging to London  
Ditto of Poop Residence  
Ditto of Raised Qr. Dk. By whom built R. Napier & Sons Destined Voyage China  
Ditto of Houses on Deck If Surveyed Afloat or in Dry Dock West India Dry Dock & Afloat  
Gross Tonnage 2484 (State Name of Dock) Years assigned. Character in Register Book.  
Crew Space, as per Rule  
Register Tonnage, cut on Beam  
Engine Room  
Reg. Tons as St'mer, cut on Bm. 1586  
Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Last Survey, No 41579 Port London S.S. Lon N°3-82 Classed 100 A 1  
REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated. Society's Load-Line (if assigned) as painted on Ship  
OR Society's Freeboard (if assigned) as painted on Ship

*This vessel has now been placed in Dry Dock the bottom examined and recoated with Paint.*

Present Condition of the	<i>Good</i>	<i>Good</i>	<i>Good</i>
Decks	<i>Good</i>	<i>Good</i>	<i>Good</i>
Waterways	<i>"</i>	<i>"</i>	<i>"</i>
Comings	<i>"</i>	<i>"</i>	<i>"</i>
Upper Deck Beams & Fastenings	<i>"</i>	<i>"</i>	<i>"</i>
Lower Deck Beams & Fastenings	<i>"</i>	<i>"</i>	<i>"</i>
Planksheers	<i>"</i>	<i>"</i>	<i>"</i>
Sheerstrakes	<i>"</i>	<i>"</i>	<i>"</i>
Topsides	<i>"</i>	<i>"</i>	<i>"</i>
Wales	<i>"</i>	<i>"</i>	<i>"</i>
Plank (Bottom) and Counter	<i>"</i>	<i>"</i>	<i>"</i>
Engine Room Skylights	<i>Good</i>	<i>Good</i>	<i>Good</i>
General Observations, Opinion as to Class, &c.	<i>Good</i>	<i>Good</i>	<i>Good</i>

Transoms, Pointers, and Crutches  
Timbers of the Frame at the openings  
Ditto Ditto at other places  
Keelsons  
Clamps and Shelves  
Ceiling  
Rudder  
Copper (or Y.M.) When put on  
(State if on Felt.)  
Cement (if Iron Ship) Cemented 1870  
Caulking of Bottom, Deck, & Waterways  
Windlass and Capstan  
Pumps  
Boats 5  
Masts, Yards, &c.  
Condition, how ascertained by observation  
Sails Sufficient  
Anchors No. of 3 B, 1 S & 2 H  
Cables part seen on deck Good  
Hawsers and Warps Sufficient  
Standing & Running Rigging  
Cargo and Main Hatchways Good  
Hatches Good

*This vessel is now in good and efficient condition and eligible in my opinion to remain as classed.*

The Amount of Entry Fee ... £ : : received by me, }  
Special ... £ : : 188

Certificate (if required)  
to be sent as per margin... } £ : :

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

Tuesday, 20th February, 1883.

*TRW*

*J. W. Miles*

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register  
Foundation