

42244

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, ...)

No. in Survey held at London Date, first Survey and Last Survey 22 July 1883
 g. Book. 558 on the Machinery of the Lord of the Isles (Number of Visits 1)
 Tonnage, Gross 2484 Built at Glasgow When built
 Ditto, Net 1581 Owners Shaw Buckley & Co Port belonging to 1878
 Diameter of Cylinder 44 76 Engines made by R Napier ? When made 1878
 Length of Stroke 48 Boilers made by When made 1878
 Pressure of Steam 75 If Surveyed Afloat or in Dry Dock Tenders & DK (State name of Dock.)
 Registered Horse Power 350 Years assigned 100 A1 Character in Register Book
 Last Survey No. Port L M C. 6. 82

Particulars of Repairs and Examination - Annual Survey
 (State cause of Repairs.)
Examined sea-cocks & connections & found them in a good condition.
One of the propeller blades has been renewed

General Observations, Opinion, and Recommendation: - As far as seen the sea connections of this vessel appear to be in a good condition and she is in my opinion eligible to remain as classed

Entry or Registering Fee... £ : :
 Survey Fee (per Section 28) ... £ - : - received by me,
 Certificate (if required) ... £ : : 188 }
 to be sent as per margin.
 (Travelling Expenses, if any, £)

C. E. Strome
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute
Assigned
Friday, 16th February, 1883.
Tuesday, 20th February. 83.

Submitted this vessel is eligible to remain as classed - Lloyd's Register Foundation

Form No. 9-3000, 1/11/81

Insert Character Precisely as in the Register Book.

LON 669-0633