

# ANNUAL SURVEYS.

42325

(Received at London Office, 15/3/83.)

No. \_\_\_\_\_ Survey held at London Date, first Survey 16 July Last Survey 7th March 1883  
(No. of Visits \_\_\_\_\_)

No. in Reg. Book on the S The Lord Warden Master Coke  
(No. of Visits \_\_\_\_\_)

194- Tonnage { Net 1237 Built at Sunderland When built 1862 5 Month.  
 Gross 1237  
 Under Dk. 1081 By whom built Pile Hay & Co Owners R & H Green

Port belonging to London Destined Voyage Australia

If Surveyed Afloat or in Dry Dock Greens S.M. & afloat  
(State Name of Dock.)

Insert Character precisely as in Register Book.

Last Survey, No. 41430 Port of London Classed 15A. 4.82  
Years assigned. Character in Register Book.  
Cent Lon Sec 77-10 1/2

Present Condition of the Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>new Eng oak</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	Masts, Yards, &c. <u>New Wood Fore Mast</u>
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	Condition, how ascertained <u>From S.M.</u>
Planksheers <u>"</u>	Keelsons <u>"</u>	Sails <u>Good</u>
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	Anchors, No. of <u>3 Nos. 12 &amp; 14 lbs</u>
Topsides <u>"</u>	Ceiling <u>"</u>	Cables <u>Part on S.M.</u>
Wales <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Y.M. Metal</u> When put on <u>1881</u>	Standing and Running Rigging <u>"</u>
Engine Room Skylights <u>"</u>	Caulking of Bottom, Deck, & Waterways <u>Patched run</u>	Cargo and Main Hatchways <u>Good</u>
Coal Bunkers, Openings, Lids, &c. <u>"</u>	Scuppers <u>Good</u>	Hatches <u>"</u>

General Observations, Opinion as to Class, &c. She is now in an efficient state and eligible to remain as classed for the present voyage as allowed by the Committee and on her return to this to undergo the Half Time survey. New Windlass Eng oak, & new Wood Fore Mast

Committee's Minute Friday, 16th March 1883. Senhouse Martindale  
 Character assigned PTB W Cour 10A Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18\_\_\_\_  
(No. of Visits \_\_\_\_\_)

No. in Reg. Book on the \_\_\_\_\_ Master \_\_\_\_\_  
(No. of Visits \_\_\_\_\_)

Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_  
 Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_

Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_

If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
(State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
Years assigned. Character in Register Book.

Present Condition of the Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame at the Openings _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Ditto ditto at other places _____	Condition, how ascertained _____
Planksheers _____	Keelsons _____	Sails _____
Sheerstrakes _____	Clamps and Shelves _____	Anchors, No. of _____
Topsides _____	Ceiling _____	Cables _____
Wales _____	Rudder _____	Hawsers and Warps _____
Plank (Bottom) and Counter _____	Copper or Y.M. _____ When put on _____	Standing and Running Rigging _____
Engine Room Skylights _____	Caulking of Bottom, Deck, & Waterways _____	Cargo and Main Hatchways _____
Coal Bunkers, Openings, Lids, &c. _____	Scuppers _____	Hatches _____

General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18\_\_\_\_

Character assigned \_\_\_\_\_ Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) Paid 18



Form No. 3 of Annual Sur. 1, when there are no repairs. 4000-16/3/82. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (If it is also sent to the Surveyors are requested not to write on or below the space for Committee's Minute.)

Insert Character precisely as in Register Book.

