

# ANNUAL SURVEYS.

424074

No. \_\_\_\_\_ Survey held at London Date, first Survey 24<sup>th</sup> April Last Survey 7<sup>th</sup> April 1883  
 (Received at London Office)  
 No. in on the SS Gracie Master J. Brown  
 Reg. Book. 356 (No. of Visits \_\_\_\_\_)  
 Tonnage { Net 884 Built at Heartlepool When built 1879 Month. \_\_\_\_\_  
 Gross 1394  
 Under Dk. 1167 By whom built E. Withy & Co Owners S. Clarke & Co  
 Port belonging to London Destined Voyage Syrie (Coal trade)  
 If Surveyed Afloat or in Dry Dock James J. Walsby & Co  
 (State Name of Dock.)

Last Survey, No. 41292 Port of Low  
 Present Condition of the  
 Decks Good Treennails Rivets Good  
 Waterways " Breasthooks and Stemson "  
 Comings " Transoms, Pointers, and Crutches "  
 Upper Deck Beams & Fastenings " Timbers of the Frame at the Openings "  
 Lower Deck Beams & Fastenings " Ditto ditto at other places "  
 Planksheers " Keelsons "  
 Sheerstrakes " Clamps and Shells "  
 Topsides " Ceiling "  
 Wales " Rudder "  
 Plank (Bottom) and Counter " Copper or Y.M. Covered When put on new  
 Caulking of "  
 Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches "  
 General Observations, Opinion as to Class, &c. Bottom is coated.  
She is now in an efficient state  
and eligible to remain as classed.

Committee's Minute \_\_\_\_\_  
 Character assigned TW 100 1883  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18

No. \_\_\_\_\_ Survey held at \_\_\_\_\_ Date, first Survey \_\_\_\_\_ Last Survey \_\_\_\_\_ 18  
 (No. of Visits \_\_\_\_\_)  
 No. in on the \_\_\_\_\_ Master \_\_\_\_\_  
 Reg. Book. \_\_\_\_\_ Year. \_\_\_\_\_ Month. \_\_\_\_\_  
 Tonnage { Net \_\_\_\_\_ Built at \_\_\_\_\_ When built \_\_\_\_\_  
 Gross \_\_\_\_\_  
 Under Dk. \_\_\_\_\_ By whom built \_\_\_\_\_ Owners \_\_\_\_\_  
 Port belonging to \_\_\_\_\_ Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock \_\_\_\_\_  
 (State Name of Dock.)

Last Survey, No. \_\_\_\_\_ Port of \_\_\_\_\_ Classed \_\_\_\_\_  
 Present Condition of the  
 Decks \_\_\_\_\_ Treennails \_\_\_\_\_  
 Waterways \_\_\_\_\_ Breasthooks and Stemson \_\_\_\_\_  
 Comings \_\_\_\_\_ Transoms, Pointers, and Crutches \_\_\_\_\_  
 Upper Deck Beams & Fastenings \_\_\_\_\_ Timbers of the Frame at the Openings \_\_\_\_\_  
 Lower Deck Beams & Fastenings \_\_\_\_\_ Ditto ditto at other places \_\_\_\_\_  
 Planksheers \_\_\_\_\_ Keelsons \_\_\_\_\_  
 Sheerstrakes \_\_\_\_\_ Clamps and Shells \_\_\_\_\_  
 Topsides \_\_\_\_\_ Ceiling \_\_\_\_\_  
 Wales \_\_\_\_\_ Rudder \_\_\_\_\_  
 Plank (Bottom) and Counter \_\_\_\_\_ Copper or Y.M. \_\_\_\_\_ When put on \_\_\_\_\_  
 Caulking of \_\_\_\_\_  
 Bottom, Deck, & Waterways \_\_\_\_\_  
 Engine Room Skylights \_\_\_\_\_ Coal Bunkers, Openings, Lids, &c. \_\_\_\_\_ Scuppers \_\_\_\_\_ Cargo and Main Hatchways \_\_\_\_\_ Hatches \_\_\_\_\_  
 General Observations, Opinion as to Class, &c. \_\_\_\_\_

Committee's Minute \_\_\_\_\_ 18 \_\_\_\_\_  
 Character assigned \_\_\_\_\_  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin) \_\_\_\_\_ Paid \_\_\_\_\_ 18