

# ANNUAL SURVEYS.

42464

No.          Survey held at London Date, first Survey 14 April Last Survey 27 April 1883  
 (Received at London Office, 2/5/83)  
 No. in on the SS Earl King Master J. Senham  
 Reg. Book. 653 (No. of Visits         )  
 Tonnage Net 1418 Built at Glasgow When built 1865 Month. 9  
Gross 2193 By whom built A. J. Inglis Owners W. Rops & Co.  
Under Dk. 1583 Port belonging to Glasgow Destined Voyage Montreal  
 If Surveyed Afloat or in Dry Dock James J. W. Lock & afloat.  
 (State Name of Dock.)

Last Survey, No. 44644 Port of Lon  
 Present Condition of the  
 Decks Good Treennails Removed Good  
 Waterways          Breasthooks and Stemson           
 Comings          Transoms, Pointers, and Crutches           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings           
 Lower Deck Beams & Fastenings          Ditto ditto at other places           
 Planksheers          Keelsons           
 Sheerstrakes          Clamps and Shelves           
 Topsides          Ceiling           
 Wales          Rudder           
 Plank (Bottom) and Counter          Copper or Y.M. Copper When put on           
 Caulking of           
 Bottom, Deck, & Waterways Good  
 Engine Room Skylights Good Coal Bunkers, Openings, Lids, &c. Good Scuppers Good Cargo and Main Hatchways Good Hatches           
 General Observations, Opinion as to Class, &c. Bottom scraped & coated about 40 rivets removed in after part and sternpost.

Classed SA SA SA SA  
 Years assigned. 100 A1  
 Character in Register Book. 4.82  
SS Lon No 3.81


She is now in an efficient state and eligible to remain as afloat. The standard chain cable has been hauled on board for the Government surveyor & has been examined by me 135 fathoms.

Committee's Minute Tuesday, 21 May, 1883  
 Character assigned 100 A1  
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)          Paid 18

No.          Survey held at          Date, first Survey          Last Survey 18  
 (No. of Visits         )  
 No. in on the          Master           
 Reg. Book.          (No. of Visits         )  
 Tonnage Net          Built at          When built           
Gross          By whom built          Owners           
Under Dk.          Destined Voyage           
 Port belonging to           
 If Surveyed Afloat or in Dry Dock           
 (State Name of Dock.)

Last Survey, No.          Port of          Classed           
 Present Condition of the  
 Decks          Treennails           
 Waterways          Breasthooks and Stemson           
 Comings          Transoms, Pointers, and Crutches           
 Upper Deck Beams & Fastenings          Timbers of the Frame at the Openings           
 Lower Deck Beams & Fastenings          Ditto ditto at other places           
 Planksheers          Keelsons           
 Sheerstrakes          Clamps and Shelves           
 Topsides          Ceiling           
 Wales          Rudder           
 Plank (Bottom) and Counter          Copper or Y.M.          When put on           
 Caulking of           
 Bottom, Deck, & Waterways           
 Engine Room Skylights          Coal Bunkers, Openings, Lids, &c.          Scuppers          Cargo and Main Hatchways          Hatches           
 General Observations, Opinion as to Class, &c.         

Committee's Minute 18  
 Character assigned           
 Surveyor to Lloyd's Register of British and Foreign Shipping.  
 Certificate (if required, to be sent as per margin)          Paid 18



(If a Steam Ship, state if a Report is also sent on the Machinery.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)  
 (Form No. 3 for Annual Survey, when there are no repairs. 4000-26/4/83.)  
 (The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)