

23/5/83

REPORT of SURVEY for REPAIRS, &c.

* 42489

(Received at London) THURSDAY 24 MAY 1883

No. in Reg. Book. *583* Survey held at *London* Date, first Survey *3 May* Last Survey *23^d May 1883*

on the *S Grasmere* Master *Raymond*

TONNAGE under Tonnage Deck <i>1180</i>	Built at <i>Whitehaven</i>	When built <i>1875</i>	YEAR. MONTH.
Ditto of Spar Deck, or Awning Deck	Owners <i>Fisher & Spott</i>	Port belonging to <i>Liverpool</i>	
Ditto of Poop	Residence		
Ditto of Raised Qr. Dk.	By whom built <i>Whitehaven Ship B Co</i>	Destined Voyage <i>New Zealand</i>	
Ditto of Houses on Deck	If Surveyed Afloat or in Dry Dock <i>Greens Lock & Afloat</i>	Part built in	
Ditto of Forecastle	(State Name of Dock)		
Gross Tonnage <i>1304</i>			
Crew Space, as per Rule			
Register Tonnage, cut on Beam <i>1246</i>			
Engine Room			
Reg. Tons as St ^r mer, cut on Bm.			

Length of Poop _____ ft. Ditto, Forecastle _____ ft. Ditto, Raised Quarter Deck _____ ft.

Last Survey, No. *28122* Port *Line* Classed *100A/3.82*
S.S. Lin No. 1.80.

REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated. Society's Load-Line (if assigned) as painted on Ship Society's Freeboard (if assigned) as painted on Ship

At present placed in the dry dock the bottom scraped and coated Renewed 37 Main Deck planks on Portside & 25 on Starboard side of Yellow Pine.

Present Condition of the				
Decks	<i>Good</i>	<i>Treenails Rivets</i>	<i>Good</i>	Windlass and Capstan <i>Good</i>
Waterways	"	Breasthooks and Stemson	"	Pumps "
Comings	"	Transoms, Pointers, and Crutches	"	Boats "
Upper Deck Beams & Fastenings	"	Timbers of the Frame at the openings	"	Masts, Yards, &c. "
Lower Deck Beams & Fastenings	"	Ditto Ditto at other places	"	Condition, how ascertained <i>From St</i>
Planksheers	"	Keelsons	"	Sails <i>Good</i>
Sheerstrakes	"	Clamps and Shells	"	Anchor No. of & Bors. <i>St & Rods</i>
Topsides	"	Ceiling	"	Cables <i>Part on St</i> <i>Good</i>
Wales	"	Rudder	"	Hawsers and Warps "
Plank (Bottom) and Counter	"	Copper <i>Coated</i> When put on <i>new</i>		Standing & Running Rigging "
Engine Room Skylights	<i>Good</i>	Cement (if Iron Ship)		Cargo and Main Hatchways <i>Good</i> Hatches "
Coal Bunker, Openings, Lids, &c.	<i>Good</i>	Caulking of Bottom, Deck, & Waterways	<i>Good</i>	
Scuppers	<i>Good</i>			

She is now in an efficient state and eligible to remain as classed.

The Amount of Entry Fee ... £ - : - : received by me, }
24/5/83 Special ... £ 1 : 1 : } *28th May 1883*
Certificate (if required) } £ : 5 :
to be sent as per margin...

Senhouse Martindale
Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £) Committee's Minute FRIDAY 25 MAY 1883 18

Character assigned *100A/3.82*

[Form No. 2 for Repairs.—1,000—8/11/82.] (If a Steam Ship, state whether or not a Report is also sent on the Machinery)

[Insert Character precisely as in Register Book.]



REPORT OF SURVEY FOR REPAIRS &c.

James



© 2021

Lloyd's Register Foundation