

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, TUESDAY 15 MAY 1883

No.

No. in Survey held at

London

Date, first Survey 21 March Last Survey 11 May 1883

Reg. Book.

6

on the

SS Tiviotdale

(No. of Visits

Master

Houston

YEAR.

MONTH.

TONNAGE under Tonnage Deck

1447

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1580

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

1008 (1018)

Built at

Greenock

When built

1882

5

Owners

R Mackill

Port belonging to

Glasgow

Residence

By whom built

R Steele

Destined Voyage

Australia

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Albert St afloat & part barge in

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Classed

Years assigned.

Character in Register Book.

Last Survey, No. 8228 Port

Leith

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Society's Load-Line (if assigned) as painted on Ship

Society's Freeboard (if assigned) as painted on Ship

At present this vessel has been fitted up for the conveyance of frozen meat from Australia. She has 7 Water-tight Bulkheads recorded in the Register Book, one of the extra Bulkheads a doorway on each side had to be cut in it, the owner or his agent asking permission of the Committee and granted by them as per Secretary's letter.

Additional Iron Pillars have been placed in the lower hold to support the engines to freeze the meat.

Present Condition of the

Decks

Good

Freonails Rivets

Good

Windlass and Capstan

Good

Waterways

"

Breasthooks and Stenson

"

Pumps

"

Comings

"

Transoms, Pointers, and Crutches

"

Boats

"

Upper Deck Beams & Fastenings

"

Timbers of the Frame at the openings

"

Masts, Yards, &c.

"

Lower Deck Beams & Fastenings

"

Ditto Ditto at other places

"

Condition, how ascertained

From St

Planksheers

"

Keelsons

"

Sails

Good

Sheerstrakes

"

Clamps and Shelves

"

Anchors No. of 3 Bbs St & Kedys

Topsides

"

Ceiling

"

Cables Part on St

Good

Wales

"

Rudder

"

Hawsers and Warps

"

Plank (Bottom) and Counter

Caulking of Bottom, Deck, & Waterways

Good

Standing & Running Rigging

"

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

General Observations, Opinion as to Class, &c.

She is now in an efficient state and eligible to remain as classed, and to have 6 Water-tight Bulkheads recorded in the Register Book as directed in the Secretary's letter to the Owner.

The Amount of Entry Fee ...

Special ...

2

2

Certificate (if required)

to be sent as per margin...

5

received by me,

28/5-1883

77.6

Senhouse Martindale.

Surveyor to Lloyd's Register of British and Foreign Shipping.

(Travelling Expenses, if any, £

Committee's Minute

FRIDAY 18 MAY 1883

18

Character assigned

Note 6 Bulkheads

TRW

© 2021

Lloyd's Register

Foundation

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.