

ANNUAL SURVEYS.

FRIDAY 25 MAY 1883

No. 570 Survey held at London Date, first Survey 17 May Last Survey 22 May 18 83
 No. in Reg. Book. 570 on the SS Mary Nixon Master M. Pap
 Net 478 Built at Newcastle When built 1865 5
 Tonnage Gross 766 By whom built Palmer Owners J Fenwick & Son
 Under Dk. 713 Port belonging to Newcastle Destined Voyage Lyme (Coal Trade)
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St
 (State Name of Dock.)

Last Survey, No. 41718 Port of London

Present Condition of the Decks <u>Good</u>	Treenails <u>Pivots</u>	Good
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	"
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	"
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	"
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	"
Planksheers <u>"</u>	Keelsons <u>"</u>	"
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	"
Topsides <u>"</u>	Ceiling <u>"</u>	"
Wales <u>"</u>	Rudder <u>"</u>	"
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Copper</u> When put on <u>now</u>	"
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	"
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	"
General Observations, Opinion as to Class, &c. <u>She is now in an efficient state and eligible to remain as classed. A small piece has been let into a cracked plate (by damage) and a doubling plate put over it.</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>


Committee's Minute TUESDAY 5 JUNE 1883 18
 Character assigned B.S. 583 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) TRW Paid 18

No. 570 Survey held at London Date, first Survey 17 May Last Survey 22 May 18
 No. in Reg. Book. 570 on the SS Mary Nixon Master M. Pap
 Net 478 Built at Newcastle When built 1865 5
 Tonnage Gross 766 By whom built Palmer Owners J Fenwick & Son
 Under Dk. 713 Port belonging to Newcastle Destined Voyage Lyme (Coal Trade)
 If Surveyed Afloat or in Dry Dock Pontoon Victoria St
 (State Name of Dock.)

Last Survey, No. 41718 Port of London Classed SS Lon W 3.81

Present Condition of the Decks <u>Good</u>	Treenails <u>Pivots</u>	Good
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	"
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	"
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame at the Openings <u>"</u>	"
Lower Deck Beams & Fastenings <u>"</u>	Ditto ditto at other places <u>"</u>	"
Planksheers <u>"</u>	Keelsons <u>"</u>	"
Sheerstrakes <u>"</u>	Clamps and Shelves <u>"</u>	"
Topsides <u>"</u>	Ceiling <u>"</u>	"
Wales <u>"</u>	Rudder <u>"</u>	"
Plank (Bottom) and Counter <u>"</u>	Copper or Y.M. <u>Copper</u> When put on <u>now</u>	"
Engine Room Skylights <u>Good</u>	Caulking of Bottom, Deck, & Waterways <u>Good</u>	"
Coal Bunkers, Openings, Lids, &c. <u>Good</u>	Scuppers <u>Good</u>	"
General Observations, Opinion as to Class, &c. <u>She is now in an efficient state and eligible to remain as classed. A small piece has been let into a cracked plate (by damage) and a doubling plate put over it.</u>	Cargo and Main Hatchways <u>Good</u>	Hatches <u>"</u>

Committee's Minute TUESDAY 5 JUNE 1883 18
 Character assigned B.S. 583 Surveyor to Lloyd's Register of British and Foreign Shipping.
 Certificate (if required, to be sent as per margin) TRW Paid 18



© 2021

Lloyd's Register Foundation

Mary Mason