

19/6/83  
Damage Repairs  
REPORT of SURVEY for REPAIRS, &c. 42594

(Received THURSDAY 21 JUNE 1883)

No.

No. in Survey held at

London

Date, first Survey 5 June

Last Survey 13 June 1883

Reg. Book.

on the

SS Annandale

(No. of Visits)

Master Atkinson

TONNAGE under Tonnage Deck

1267

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

1607

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St'mer, cut on Bm.

1041

Built at

Hartlepool

When built

1878

MONTH.

Owners

Steel Young & Co

Port belonging to

London

Residence

By whom built

E. Withy & Co

Destined Voyage

Cardiff

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Pontoon Victoria Stk

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Last Survey, No. 6011 Port

Rpt

Classed 100A1 1883

SS Goff no 183

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Society's Load-Line (if assigned) as painted on Ship

Society's Freeboard (if assigned) as painted on Ship

At present owing to damage:  
The Stem Frame taken out and welded  
at the after part of the keel (being broken.)  
and replaced and rivetted.  
Port Bow. 2 broken plates at Bilges renewed,  
and butt straps to ditto.  
2 Frames shifted and well butt strapped,  
1 bent frame and 3 reverse frames made fair.

Bottom &c coated

Present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Engine Room Skylights

General Observations, Opinion as to Class, &c.

Good

Treenails Rivets

Breasthooks and Stemson

Transoms, Pointers, and Crutches

Timbers of the Frame at the openings

Ditto Ditto at other places

Keelsons

Clamps and Shelves

Ceiling

Rudder

Copper (or Iron) coated When put on

(State if on Red.)

Cement (if Iron Ship)

Caulking of Bottom, Deck, & Waterways

Coal Bunker, Openings, Lids, &c.

Scuppers

Cargo and Main Hatchways

Hatches

Good

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of 3 Bns. 12 & 14 kds

Cables Part seen

Hawsers and Warps

Standing & Running Rigging

Cargo and Main Hatchways

Hatches

Good

Good

Good

Good

From Stk

Good

Good

Good

Good

Good

Good

Good

The Amount of Entry Fee ...

17/6 Special ...

Certificate (if required)

to be sent as per margin...

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

TUESDAY 26 JUNE 1883

18

received by me,

30 June 1883

Senhouse Martindale

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2021

Lloyd's Register

Foundation

ROBT. EDMD. TAYLOR & SON, Commercial Steam Printers, 19, Old Street Goswell Road, London.

Low 670-0399

Amundale



© 2021

Lloyd's Register  
Foundation