

REPORT of SURVEY for REPAIRS, &c.

No.

No. in Survey held at
Reg. Book.

London

Date, first Survey 5th July Last Survey

1883

156 on the *Iron S.S. Malaya*

(No. of Visits)

Master *A Russell*

Official Number
TONNAGE under Tonnage Deck
Ditto of Spar Deck, or Awning Deck
Ditto of Poop
Ditto of Raised Qr. Dk.
Ditto of Houses on Deck
Ditto of Forecastle
Gross Tonnage
Crew Space, as per Rule
Register Tonnage, cut on Beam
Engine Room
Reg. Tons as St' mer, cut on Bm.

1420

1614

1024

Built at *W. Hartlepool*

When built 1876

YEAR. MONTH.

Owners *J. Hall & Co*

Port belonging to *London*

Residence

By whom built *W. Gray & Co*

Destined Voyage *Spain*

If Surveyed Afloat or in Dry Dock

(State Name of Dock)

Bentley St

Length of Poop

ft. Ditto, Forecastle

ft. Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No. *41644* Port *Spain*

Classed

100A1

S.S. Lon to 1.80

REPAIRS, OR EXAMINATION AS PER RULE

Cause of Repairs to be clearly stated.

Society's Freeboard (if assigned) as painted on Ship

State dates of any letters respecting this case

Bottom recoated - Chain Cables raised out and Examined 270 fms

Instructions were given for the marking of the freeboard on the sides of this vessel and the freeboard is stated to have been marked in but the vessel went to sea before an opportunity was given to examine the same.

Present Condition of the

Decks

Good

Greenails

Revised

Good

Windlass and Capstan

Good

Waterways

Breasthooks and Stems

Pumps

Comings

Transoms, Pointers, and Crutches

Boats *5th*

Upper Deck Beams & Fastenings

Timbers of the Frame at the openings

Masts, Yards, &c.

Lower Deck Beams & Fastenings

Ditto Ditto at other places

Condition, how ascertained *from 100*

Plank sheers

Keelsons

Sails

Sheerstrakes

Clamps and Shells

Anchors No. of *3 B. 15 + 2 K*

Topsides

Ceiling

Cables

Wales

Rudder

Hawsers and Warps *4 wire 4 others*

Plank (Bottom) and Counter

Copper (or Y.M.) When put on

Standing & Running Rigging

Engine Room Skylights

Cement (if Iron Ship)

Good Cargo and Main Hatchways

General Observations, Opinion as to Class, &c.

Caulking of Bottom, Deck, & Waterways

Good Hatches

Coal Bunker, Openings, Lids, &c.

Good Scuppers

She is now in good condition and in my opinion eligible to continue as Classed

The Amount of Entry Fee ... £

received by me,

Special ... £

188

Certificate (if required)
to be sent as per margin...

See freeboard report for fees 15/8/83

(Travelling Expenses, if any, £)

Committee's Minute

Character assigned

FRIDAY 27 JULY 1883

100A1

W. C. Davey
Surveyor to Lloyd's Register of British and Foreign Shipping.
A. H. Truocott (in reference to freeboard)



© 2021

Lloyd's Register Foundation

ROBERT EDMUND TAYLOR & SON, Commercial Steam Printers, 10, Old Street, Goswell

LOW 670-0470

[Form No. 2 for Repairs, 1900-1901.]

(The Surveyors are requested not to write on or below the space for Committee's Minute.)

(Insert Character precisely as in Register Book.)