

# REPORT of SURVEY for REPAIRS, &c.

FRIDAY 27 JULY 1883

(Received at London Office)

No. in Survey held at London Date, first Survey 20<sup>th</sup> July Last Survey 20<sup>th</sup> July 1883.  
 Reg. Book. 67 on the Iron Screw Steamer "Oceano" (No. of Vessels) Master J. Walker.

TONNAGE under Tonnage Deck 934  
 Ditto of Spar Deck, or Awning Deck  
 Ditto of Poop  
 Ditto of Raised Qr. Dk.  
 Ditto of Houses on Deck  
 Ditto of Forecastle  
 Gross Tonnage 1004  
 Crew Space, as per Rule  
 Register Tonnage, cut on Beam  
 Engine Room  
 Reg. Tons as S<sup>r</sup> mer, cut on Bm. 650  
 Length of Poop ft. Ditto, Forecastle ft. Ditto, Raised Quarter Deck ft.

Built at Middlesbro' When built 1871 YEAR. MONTH. 8<sup>th</sup>  
 Owners Tatham & Co Port belonging to London  
 Residence  
 By whom built Backhouse & Dixon. Destined Voyage Cardiff  
 If Surveyed Afloat or in Dry Dock Afloat in the Thames off Seaward's Works Millwall  
 (State Name of Dock) Years assigned. Character in Register Book.

Last Survey, No. 5940 Port Sept S.L. Lon. N<sup>o</sup> 3-78. S.L. Off. N<sup>o</sup> 1-82. Classed 100 A.1  
 REPAIRS, OR EXAMINATION AS PER RULE Cause of Repairs to be clearly stated. Society's Freeboard (if assigned) as painted on Ship 1-5 to main deck  
 State dates of any letters respecting this case Freeboard. 10, 82.  
2-7 to awning deck  
1-1 fresh water to main deck

The freeboard marked on the sides of this vessel has been examined and found to correspond with that assigned by the Committee.

Present Condition of the Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame at the openings	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Ditto Ditto at other places	Condition, how ascertained
Planksheers	Keelsons	Sails
Sheerstrakes	Clamps and Shelves	Anchor No. of
Topsides	Ceiling	Cables
Wales	Rudder	Hawsers and Warps
Plank (Bottom) and Counter	Copper (or Y.M.) When put on (State if on Felt.)	Standing & Running Rigging
Engine Room Skylights	Cement (if Iron Ship)	Cargo and Main Hatchways
Coal Bunker, Openings, Lids, &c.	Caulking of Bottom, Deck, & Waterways	Hatches
Scuppers		

General Observations, Opinion as to Class, &c.  
She appears to be eligible to remain as classed

18.0  
1.5  
8.9

The Amount of Entry Fee ... £ : : received by me, }  
 Special ... £ : : 188 }  
 Certificate (if required) } £ : :  
 to be sent as per margin... }

(Travelling Expenses, if any, £ )  
 Committee's Minute Tuesday, 31st JULY, 83.

Character assigned Not to freeboard  
 J. H. Truscott.  
 Surveyor to Lloyd's Register of British and Foreign Shipping.