

# Report of Survey for Repairs of Engines and Boilers.

42659

(Received at London Office, FRIDAY 13 JULY 1883)

No. \_\_\_\_\_

No. in Reg. Book. *190* Survey held at *London* Date, first Survey *27 June* Last Survey *5 July* 188*3*

on the Machinery of the *S. S. Despatch* (Number of Visits *5*)

Tonnage, Gross *734* Built at *Shields Newcastle* When built *1863*

Ditto, Net *465* Owners *J. Fenwick & Co* Port belonging to *London*

Diameter of Cylinder *25 48* Engines made by *Compounded Ric. & W.* When made *1875*

Length of Stroke *30* Boilers made by \_\_\_\_\_ When made *1875*

Pressure of Steam *70*

Registered Horse Power *90*

If Surveyed Afloat or in Dry Dock *Pontoon* (State name of Dock.)

Last Survey No. \_\_\_\_\_ Port \_\_\_\_\_

Years assigned. *3. 82* Character in Register Book. *A 1.*

*L. M. C. 3. 82*

Particulars of Repairs and Examination *Annual Survey of Boilers and New Propeller*

Examined Leucosacks & connections and found them in a good condition. The tailshaft was drawn and found to be in a good condition. A new propeller has been fitted. Lignum vitae has been fitted in stern tube instead of the brass liner. Several tubes in condenser have been renewed.

Examined 2 main boilers and Superheaters and found them in a good condition. A few rivets and seams have been recaulked.

Examined lever weighted safety valves, slide valves cylinders & pumps and found them in a good condition.

Examined crankshaft & found it in a good condition.

General Observations, Opinion, and Recommendation:— The machinery of this vessel appears to be in a safe working condition and the vessel is in my opinion eligible to have the notification L. M. C. 4. 82 recorded in the Register Book.

Entry or Registering Fee... £ : :  
 Survey Fee (per Section 28) *18/7* £ *2 : 2* : — received by me, *J. F. C.*  
 Certificate (if required) ... £ : : *20/7* 1883

*J. Brown*  
 Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

TUESDAY 17 JULY 1883 188

Committee's Minute \_\_\_\_\_  
 Assigned *L. M. C. 7. 83*

Form No. 9-3010-8/83. (The Surveyors are requested not to write on or below the space for Committee's Minute.) (State if Report is also sent on the Hull of the Ship. Condition of Engines and Boilers, and subsequent Repairs and Examinations, to be clearly stated.)

Insert Character precisely as in the Register Book.



Submitted that this vessel is  
eligible to Lewis Lloyd M.C.  
7.83. recorded in the Register  
Book.

MO 12-7-83



© 2021  
Lloyd's Register  
Foundation